

AD-A104 997

PRC CONSOER TOWNSEND INC ST LOUIS MO F/6 13/13
NATIONAL DAM SAFETY PROGRAM, HAUCK LAKE DAM (MO 109891), MISSOURI-ETC(U)
SEP 80 W G SHIFRIN DACW43-80-C-0094

NL

UNCLASSIFIED

1 of 2

AD
A104997



SECRET

AD A104997

LEVEL II

(1)

MISSOURI - KANSAS CITY RIVER BASIN

HAUCK LAKE DAM
CALLAWAY COUNTY, MISSOURI
MO. 10989



PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

"Original contains color
plates: All DTIC reproductions
will be in black and
white"



United States Army
Corps of Engineers


...Serving the Army
...Serving the Nation

St. Louis District

"Original contains color
plates: All DTIC reproductions
will be in black and
white"

PREPARED BY: U. S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI



SEPTEMBER, 1980

81 10 2 153

DTIC FILE COPY

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
	AD-A104997	
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Hauck Lake Dam (MO 10989) Callaway County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Consoer, Townsend and Associates, Ltd.		6. PERFORMING ORG. REPORT NUMBER
		8. CONTRACT OR GRANT NUMBER(s) DACW43-80-C-0094
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		12. REPORT DATE September 1980
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) (6) National Dam Safety Program. Hauck Lake Dam (MO 10989), Missouri - Kansas City River Basin, Callaway County, Missouri. Phase I Inspection Report.		13. NUMBER OF PAGES Approximately 120
16. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) Approved for release; distribution unlimited.		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)



Accession For
BORN GARY
1918-1919
GARY, GARY
JANUARY 1918

Born []
District []
[] [] [] []
Dist Special

K

HAUCK LAKE DAM
CALLAWAY COUNTY, MISSOURI

MISSOURI INVENTORY NO. 10989

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED BY
CONSOER, TOWNSEND AND ASSOCIATES, LTD.
ST. LOUIS, MISSOURI
AND
PRC ENGINEERING CONSULTANTS, INC.
ENGLEWOOD, COLORADO
A JOINT VENTURE

UNDER DIRECTION OF
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
FOR
GOVERNOR OF MISSOURI

SEPTEMBER 1980

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Hauck Lake Dam, Missouri Inv. No. 10989
State Located: Missouri
County Located: Callaway
Stream: An unnamed tributary of Stinson Creek
Date of Inspection: June 4, 1980

Assessment of General Condition

Hauck Lake Dam was inspected by the engineering firms of Consoer, Townsend and Associates, Ltd. and PRC Engineering Consultants, Inc. (A Joint Venture) of St. Louis, Missouri according to the U. S. Army Corps of Engineers "Engineer Regulation No. 1110-2-106" and additional guidelines furnished by the St. Louis District of the Corps of Engineers. Based upon the criteria in the guidelines, the dam is in the high hazard potential classification, which means that loss of life and appreciable property damage could occur in the event of failure of the dam. Within the estimated damage zone of four miles downstream of the dam are six dwellings, one building, a junkyard, a shed, a school and a park, all of which may be subjected to flooding, with possible damage and/or destruction, and loss of life. Hauck Lake Dam is in the small size classification since it is less than 40 feet in height and impounds less than 1,000 acre-feet of water.


Our inspection and evaluation indicate that the reservoir/spillway system of Hauck Lake Dam does meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. Hauck Lake Dam being a small size dam with a high hazard

potential is required by the guidelines to be able to pass from one-half of the Probable Maximum Flood to the Probable Maximum Flood (PMF) without overtopping the dam. Nevertheless, considering the number of inhabited dwellings, the school and the park, located downstream of the dam, the PMF is considered the appropriate spillway design flood for Hauck Lake Dam. It was determined that the reservoir/spillway system can accommodate approximately 60 percent of the Probable Maximum Flood before overtopping of the dam occurs. Therefore, the reservoir/spillway system is considered to be inadequate. Our evaluation also indicates that the reservoir/spillway system will accommodate the one-percent chance flood (100-year flood) without overtopping the dam.

The Probable Maximum Flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorological and hydrologic conditions that are reasonably possible in the region.


Hauck Lake Dam and its appurtenant structures are in fair condition. However, some deficiencies were noted by the inspection team which could affect the safety of the dam and appurtenant structures. These items are as follows: possible seepage at the toe of the dam, the wave erosion on the upstream berm, cracks on the top of the dam, rodent activity on the embankment and on the emergency spillway training berm, some minor surface erosion on the embankment slopes, the need for proper maintenance of the vegetation on the embankment, the accumulation of driftwood near the emergency spillway, the lack of adequate erosion protection in the emergency spillway channel, possible leakage along the principal spillway pipe, a need for periodic inspection by a qualified engineer and a lack of a maintenance schedule. The lack of seepage and stability analyses on record is also a deficiency that should be corrected.

It is recommended that the owner take action to correct or control the several deficiencies described above in the near future.



Walter G. Shifrin, P.E.





Overview of Hauck Lake Dam

NATIONAL DAM SAFETY PROGRAM

HAUCK LAKE DAM, I.D. No. 10989

TABLE OF CONTENTS

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 1	PROJECT INFORMATION	1
	1.1 General	1
	1.2 Description of Project	2
	1.3 Pertinent Data	7
SECTION 2	ENGINEERING DATA	10
	2.1 Design	10
	2.2 Construction	10
	2.3 Operation	11
	2.4 Evaluation	11
SECTION 3	VISUAL INSPECTION	13
	3.1 Findings	13
	3.2 Evaluation	19

TABLE OF CONTENTS

(Continued)

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 4	OPERATION PROCEDURES	22
	4.1 Procedures	22
	4.2 Maintenance of Dam	22
	4.3 Maintenance of Operating Facilities	22
	4.4 Description of Any Warning System in Effect	22
	4.5 Evaluation	23
SECTION 5	HYDRAULIC/HYDROLOGIC	24
	5.1 Evaluation of Features	24
SECTION 6	STRUCTURAL STABILITY.	28
	6.1 Evaluation of Structural Stability.	28
SECTION 7	ASSESSMENT/REMEDIAL MEASURES.	31
	7.1 Dam Assessment	31
	7.2 Remedial Measures.	33

TABLE OF CONTENTS

(Continued)

LIST OF PLATES

	<u>Plate No.</u>
LOCATION MAP	1
PLAN AND ELEVATION OF DAM	2
EMBANKMENT SECTION AND SPILLWAY PROFILE	3
SCS DESIGN DRAWINGS	4-5
SCS HYDROLOGIC AND HYDRAULIC DESIGN CALCULATIONS	6
GEOLOGIC MAP	7-8
SEISMIC ZONE MAP	9

APPENDICES

APPENDIX A - PHOTOGRAPHS

APPENDIX B - HYDROLOGIC AND HYDRAULIC COMPUTATIONS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

HAUCK LAKE DAM, Missouri Inv. No. 10989

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The Dam Inspection Act, Public Law 92-367 of August, 1972, authorizes the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspections. Inspection for Hauck Lake Dam was carried out under Contract DACW 43-80-C-0094 between the Department of the Army, St. Louis District, Corps of Engineers, and the engineering firms of Consoer, Townsend & Associates, Ltd., and PRC Engineering Consultants, Inc. (A Joint Venture), of St. Louis, Missouri.

b. Purpose of Inspection

The visual inspection of Hauck Lake Dam was made on June 4, 1980. The purpose of the inspection was to make a general assessment regarding the structural integrity and operational adequacy of the dam embankment and its appurtenant structures.

c. Scope of Report

This report summarizes available pertinent data relating to the project, provides a summary of visual observations made during the field inspection, gives an assessment of hydrologic and hydraulic conditions at the site, presents an evaluation of the

structural adequacy of the various project features and appraises the general condition of the dam with respect to safety.

Subsurface investigations, laboratory testing and detailed analyses were not within the scope of this study. No warranty as to the absolute safety of the project features is implied by the conclusions presented in this report.

It should be noted that in this report the reference to the left or right abutments is viewed as looking downstream. Where left abutment or left side of the dam is used in this report, this also refers to the north abutment or side, and right to the south abutment or side.

d. Evaluation Criteria

The inspection and evaluation of the dam is performed in accordance with the U.S. Army Corps of Engineers "Engineer Regulation No. 1110-2-106" and additional guidelines furnished by the St. Louis District office of the Corps of Engineers for Phase 1 Dam Inspection.

1.2 Description of the Project

a. Description of Dam and Appurtenances

The following description is based upon observations and measurements made during the visual inspection. Two design drawings were located and are included as part of this report (see Plates 4 and 5). Any discrepancies between our field notes and the drawings are noted in Section 2.1 in this report. No major discrepancies were observed.

The dam is an earthfill structure between earth abutments. A plan and elevation of the dam is shown on Plate 2, and Photos 1 through 3 show views of the dam. The dam consists of two straight segments of embankment angled at approximately 15 degrees to each other and connected by a smooth curve. The major portion of the embankment has a bearing of approximately N 10° W and an axis length of 358 feet between the emergency spillway and the point of intersection of the two segments. The other portion has a bearing of approximately N 25° W and an axis length of 218 feet between the point of intersection of the two segments and the left abutment. The top of dam has a width of 12 feet and a total length of 576 feet between the emergency spillway and the left abutment. The top of dam was measured as level and has the assumed elevation of 842 feet above mean sea level (M.S.L.) The maximum structural height of the dam was measured to be 23 feet. A berm, varying in width from 5 to 10 feet, was constructed on the upstream slope 3.25 feet below the top of dam. The berm sloped down towards the reservoir on an average of 7.5 percent. The upstream slope was measured as 1 vertical to 2.5 horizontal (1V to 2.5H) from the top of dam to the berm and nearly vertical from the berm to the water surface. The downstream slope was measured to be 1V to 2H.

The dam was constructed with a double spillway system; the first is considered the principal spillway and operates as a closed conduit when flowing full, and the second is considered the emergency spillway and operates as an open channel.

The principal spillway was assembled from lengths of steel pipe welded together and laid through the embankment on a grade of 10 percent. Approximately 90 feet of pipe was placed on a bearing of N 63° E through the major portion of the embankment. The inside diameter of the pipe was measured as 10.5 inches. The drawings also reveal the locations of two or three metal anti-seepage collars as starting 15 feet from the beginning of the pipe and using a 15 foot spacing; the collars were to be a minimum of 5-foot square. The inlet for this spillway pipe, which is located

about 220 feet to the left of the emergency spillway, consists of a vertical, 21-inch inside diameter, 10-foot long welded steel standpipe. The standpipe rises into the berm area and has a crest elevation of 838 feet above M.S.L. An anti-vortex device approximately 3.5 feet long and 1 foot high, is fixed across the inlet (see Photo 6). Water flowing through the pipe would outlet into a discharge pool after a vertical fall of about two feet (see Photo 7).

The emergency spillway channel, which is cut into the right side of the dam, has a 55-foot top width, a 23-foot bottom width, and side slopes of approximately 1V to 6H. The crest of the spillway is 2.6 feet lower than the top of dam and about 1.4 feet higher than the principal spillway crest. As water progresses over the crest, (the crest invert is level for 34 feet) it flows into a large discharge channel with an 18 percent slope, before emptying into the County Highway F drainage channel (see Photo overview). A berm was constructed to form the left side of the discharge channel (see Photo 3). The discharge channel is earthen with a swale bottom and the highway drainage channel has a concrete lining (see Photo 9 and overview). Eventually, the excess flow from the emergency spillway is directed under the above mentioned highway via a 4-foot by 5-foot concrete box culvert (see Photo 11).

No low level drains or outlet works were provided for this dam.

b. Location

Hauck Lake Dam is located in Callaway County of the State of Missouri on an unnamed tributary of Stinson Creek, about 2 miles west of the city of Fulton. The axis of the dam is situated parallel to and approximately 200 feet southwest of County Highway F. The dam is located in the northwest quadrant of Section 18 of Range 9 West, Township 47 North as shown on the Fulton, Missouri Quadrangle (7.5 minute series) sheet.

Hauck Lake Dam impounds less than 1000 acre-feet and more than 50 acre-feet which classifies it as a "small" size dam. However, the maximum structural height of the dam is less than 25 feet which is the minimum requirement for a structure to be classified as a dam. Nevertheless, the size classification is determined by either the storage or height, whichever gives the larger size category. Therefore, the size classification is determined to fall within the "small" category according to the "Engineer Regulation No. 1110-2-106, Appendix D" by the U.S. Department of the Army, Office of the Chief Engineer.

d. Hazard Classification

The dam has been classified as having a "high" hazard potential in the National Inventory of Dams, on the basis that in the event of failure of the dam or its appurtenances, excessive damage could occur to downstream property, together with the possibility of the loss of life. From a visual inspection of the downstream area, our findings concur with this classification. There are six dwellings, one building, two sheds, one school, a junkyard and a park within the estimated damage zone, which extends approximately four miles downstream of the dam (see Photos 13 and 14).

e. Ownership

Hauck Lake Dam is owned privately by Mr. Gordon K. Hauck. The mailing address is as follows: Mr. Gordon K. Hauck, R.R. 4, Fulton, Missouri, 65251.

f. Purpose of Dam

The dam was built primarily for recreational purposes.

g. Design and Construction History

Hauck Lake Dam was designed by the Soil Conservation Service of Callaway County, Missouri in 1973. According to Mr. Hauck, the dam was built in 1974 by Leroy Garriot Excavation Company of Fulton, Missouri.

h. Normal Operational Procedures

Normal procedure at Hauck Lake Dam is to allow the reservoir to remain as full as possible while the water level is controlled by rainfall, runoff, evaporation and the elevation of the principal spillway crest.

1.3 Pertinent Data

a. Drainage Area (square miles):. 0.15

b. Discharge at Damsite

Estimated experienced maximum flood (cfs): Unknown

Estimated ungated spillway capacity with
reservoir at top of dam elevation (cfs): 418

c. Elevation (Feet above MSL)

Top of dam 842.0 (Assumed)

Spillway crest:

Principal Spillway 838.0

Emergency Spillway 839.4

Normal Pool: 838.0

Maximum Experienced Pool:. Unknown

Observed Pool: 837.2

d. Reservoir

Length of pool with water surface
at top of dam elevation (feet):. 1100

e. Storage (Acre-Feet)

Top of dam 176

Spillway crest:

Principal Spillway 104

Emergency Spillway 131

Normal Pool: 104

Maximum Experienced Pool:. Unknown

Observed Pool: 86

f. Reservoir Surfaces (Acres)

Top of dam 21

Spillway crest:

Principal Spillway 15

Emergency Spillway.	17
Normal Pool:	15
Maximum Experienced Pool:.	Unknown
Observed Pool:	14

g. Dam

Type.	Earthfill
Length:.	576 feet
Structural Height:	23 feet
Hydraulic Height:	23 feet
Top width:	12 feet
Side slopes:	
Downstream	1V to 2H (measured)
Upstream	1V to 2.5H (from the top of dam to edge of the berm) and near vertical (from the berm to the water surface) (measured)
Zoning:	Homogenous
Impervious core:	NA
Cutoff:	Unknown
Grout curtain:	Unknown
Volume:	14,862 cu.yds. (from design drawing)

h. Diversion and Regulating Tunnel None

i. Spillway

Type:	
Principal Spillway	Drop inlet, uncontrolled
Emergency Spillway	Earthcut channel, uncontrolled
Length of crest:	
Principal Spillway	5.5 feet (21-inch diameter standpipe)
Emergency Spillway	23 feet

Principal Spillway 838.0
Emergency Spillway 839.4
 j. Regulating Outlets None

SECTION 2: ENGINEERING DATA

2.1 Design

The Soil Conservation Service of Callaway County, Missouri has made available a set of surveying notes, two design drawings of the principal spillway and hydrologic and hydraulic computations. The drawings (dated May, 1973) show a profile along the centerline of the principal spillway and details of the drop inlet structure. The two design drawings are presented in this report as Plates 4 and 5 and the hydraulic calculations are shown on Plate 6.

According to the design drawings, the upstream slope was 1V to 3H and a 10-foot wide berm was located at 3 feet below the top of dam; however, field measurements resulted in an upstream slope of 1V to 2.5H and a berm, varying in width from 5 to 10 feet, located 3.25 feet below the top of dam. The design drawings also utilized an 18-inch inside diameter standpipe and a 12-inch inside diameter outlet pipe for the principal spillway; however, field measurements showed that a 21-inch inside diameter standpipe and a 10.5-inch inside diameter outlet pipe were used. It was also difficult to tell from the drawings whether two or three collars were constructed along the principal spillway outlet pipe.

2.2 Construction

No data are available concerning the construction of the dam and appurtenant structures.

2.3 Operation

No operation records are available for Hauck Lake Dam.

2.4 Evaluation

a. Availability

The availability of engineering data is poor and consists only of surveying notes, two design drawings of the principal spillway, hydrologic and hydraulic computations, a general soils map of the State of Missouri published by the Soil Conservation Service, State Geological Maps and U.S.G.S. quadrangle sheets. No information was available on construction or operation of the dam.

b. Adequacy

The available engineering data did not allow for a definitive review and evaluation. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing and evaluating design, operation and construction data, but is based primarily on visual inspection, past performance history and present condition of the dam. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

c. Validity

The only valid engineering data are the surveying notes, the two design drawings and the hydraulic computations obtained from the Soil Conservation Service. Only minor discrepancies between our field notes and the design drawings were noted and are described in Section 2.1. The hydraulic calculations show that the dam and

spillways were designed to pass at least the 50-year flood (two-percent chance flood). From our calculations (see Section 5.1d), it was determined that the dam and spillways are capable of passing the 100-year flood (one-percent chance flood) without overtopping the dam.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

A visual inspection of the Hauck Lake Dam was made on June 4, 1980. The following persons were present during the inspection:

<u>Name</u>	<u>Affiliation</u>	<u>Disciplines</u>
Mark Haynes, P.E.	PRC Engineering Consultants, Inc.	Project Engineer, Soils and Mechanical
Jerry Kenny	PRC Engineering Consultants, Inc.	Hydraulics and Hydrology
Robert McLaughlin, P.E.	PRC Engineering Consultants, Inc.	Civil
Razi Quraishi, R.P.G.	PRC Engineering Consultants, Inc.	Geology
Kevin Blume	Consoer, Townsend & Assoc., Ltd.	Civil and Structural

Specific observations are discussed below.

b. Dam

The overall condition of the dam appeared to be fair. However, some items of concern were observed and are described below.

The top of dam is adequately protected against surface erosion by an unmaintained vegetative cover. The top of dam is used occasionally as a farm road and consequently, tire tracks due to vehicular traffic were observed. No tire ruts or depressions which are sometimes associated with vehicular traffic across earthen structures were observed (see Photo 2). Some noncontinuous longitudinal and transverse cracks were measured up to 4 inches deep and 1/4 of an inch wide. No depressions indicating localized settlement of the dam were observed. No misalignment in either the vertical or horizontal directions was apparent. No evidence was observed indicating that the dam has ever been overtopped.

The upstream slope of the dam has no riprap protection and, consequently, a considerable amount of damage to the edge of the berm due to wave erosion has occurred. The erosion due to wave action has cut into the berm and has reduced its width to 5 feet in some areas. The berm and the slope above the berm are protected with an unmaintained grass cover (see Photo 1). In some areas, the grass cover was sparse and, consequently, some minor surface erosion has occurred. No large erosion gullies were observed. No depressions, bulges or cracks indicative of major slope or foundation movement were observed. Burrows approximately 1 inch in diameter were observed on the slope.

The downstream slope of the dam is covered by an unmaintained grass cover (see Photo 3). The grass cover was sparse in some areas and, consequently, minor surface erosion and some shallow surface scarps due to sloughing were noticed. A large area was observed downstream of the toe where no vegetative growth has occurred (see Photo 9). The area, according to Mr. Hauck, was a

coal spoil pile which was removed before the construction of the dam. The area is located just to the left of the service spillway outlet. The toe of the dam in this area is unprotected and, consequently, some erosion has occurred (see Photo 4). The scarp due to the erosion extends continuously along the toe in this area. Two areas of possible seepage were found near the toe of the slope. Boggy ground, standing water and cattails were observed in the two areas. One of the two areas was located approximately 100 feet to the left of the emergency spillway and the other approximately 218 feet to the right of the left abutment. No measurable seepage was observed. No bulges, depressions or cracks indicative of major slope or foundation movement were apparent. A comprehensive inspection of the entire embankment was hampered due to the unmaintained cover of grass.

Both abutments slope gently upward from the crest. No seepage, erosion or instabilities were observed on either abutment.

c. Project Geology and Soils

(1) Project Geology

The damsite is located on an unnamed tributary of Stinson Creek in the Dissected Till Plains Section of the central Lowland Physiographic Province. Loess-mantled Kansas drift covers the surface of most of the Dissected Till Plains Section. This section is distinguished from the Young Drift Section to the north and from the Till Plains on the east by the stage it has reached in the post-glacial erosion cycle. Broadly generalized, this section is a nearly flat till plain submature to mature in its erosion cycle.

The topography at the damsite is flat to rolling with V- to U-shaped valleys. Elevation ranges from 850 feet above M.S.L. at the damsite to 880 feet above M.S.L. nearly 1 mile southwest of the damsite. Stockpiles of coal waste from the strip mining operations are located approximately 0.75 miles northeast from the damsite.

The reservoir slopes are in the range of 5° from the horizontal at the western and northern sides, and between 10° and 16° from the horizontal at the southern side of the reservoir. The area near the damsite is covered with slope wash deposits of glacial-fluvial and loess origins consisting of mottled reddish brown to gray, silty clay.

The regional bedrock geology beneath the glacial outwash deposits in the damsite area, as shown on Geologic Map of Missouri (1979) (see Plate 7), consists of Pennsylvanian undifferentiated rocks and the Pennsylvanian Marmaton-Cherokee Group (cyclic deposits of shale, limestone, and sandstone), the Mississippian age Burlington Formation (cherty, grayish brown, sandy limestone), the Mississippian Chouteau Group, the Devonian Sulphur Springs Group (Bushberg Sandstone, Glen Park Limestone, Grassy Creek Shale), and Ordovician rocks consisting of Maquoketa Shale, Kimmswick Limestone, St. Peter Sandstone, Powell Dolomite and Roubidoux Formation.

The predominant bedrock near the damsite, underlying the glacial-fluvial deposits, are the Pennsylvanian undifferentiated rocks and cyclic deposits of shale, limestone and sandstone of the Marmaton Group. Inlet and outlet areas of the unnamed tributary of Stinson Creek exhibit quaternary alluvium.

No faults have been identified in the vicinity of the damsite. The closest trace of a fault to the damsite is the Kingdom City Fault nearly 4 miles northeast of the damsite. The Kingdom City Fault had its last movement in post-Ordovician time. Thus the fault has no effect on the damsite.

Hauck Lake Dam consists of a homogenous earthfill embankment, a drop inlet principal spillway with a metallic outlet pipe located near the mid-section of the embankment, and an emergency spillway located at the right abutment end of the embankment.

No boring logs or construction reports were available which would indicate foundation conditions encountered during the construction. Based on the visual inspection, the embankment probably rests on glacial-fluvial deposits (reddish brown, silty clay) and the principal spillway drop inlet and outlet pipe probably rest on compacted embankment. The emergency spillway was cut into the compacted embankment fill (mottled grayish red, silty clay).

(2) Project Soils

According to the "Missouri General Soil Map and Soil Association Description" published by the Soil Conservation Service, the materials in the general area of the dam belong to the soil series of Weller - Keswick - Lindley - Mandeville in the Central Mississippi Valley Wooded Slopes forest. The soils are basically formed from loess, glacial till and weathered shale. The permeability of these soils ranges from slow to moderate. The Lindley soil is generally quite susceptible to erosion. If the Lindley soil type was used in the embankment, the potential of failure of the embankment would be increased due to erosion during overtopping.

Materials removed from the upstream and downstream slopes of the embankment appeared to be a light brown, mottled yellow, red and gray, silty clay with some fine to medium sand. Based upon the Unified Soil Classification System, the soil would probably be classified as a CL. This is an impervious soil type, which generally has the following characteristics: a coefficient of permeability less than 1.0 foot per year, medium shear strength, and a high resistance to piping.

d. Appurtenant Structures

(1) Principal Spillway

The principal spillway is a drop inlet type spillway. On the day of the inspection, there was no flow over the crest; in fact, the water level was almost a foot below the crest. However, water was observed dripping from the outlet end of the pipe. A metal patch was welded to the inside of the standpipe, as if to repair a possibly corroded area; the standpipe and the anti-vortex device are not protected against rust and corrosion. The inside of this spillway was not accessible for inspection; however, from the design sheet it can be seen that the standpipe is welded to a flat metal base plate, 3.5-feet square and $\frac{3}{8}$ of an inch thick. Also, the conduit protrudes through and into the riser pipe, as noted from the field inspection. The outlet end of the spillway pipe emerges from the embankment at the toe of the dam with about 15 feet of the conduit exposed. This section of the pipe has a black protective coating, albeit in shreds (possibly worn off from the weather), and the last 10 feet of the pipe have an anomalous curvature as though inherent in the structure of the pipe (see Photo 7). Some apparent corrosion was observed on the inside of the principal spillway standpipe, and rust covered the anti-vortex device and what could be seen of the standpipe (see Photo 6).

(2) Emergency Spillway

The emergency spillway crest is bare in spots and is generally sparsely covered with a protective growth of grass; some surface erosion has occurred and the inlet area is somewhat obstructed with a growth of reeds (see Photo 8). The remainder of the discharge channel is well protected with a tall growth of grass as is the highway drainage channel with a concrete lining. There is a fairly good sized rodent hole (see Photo 5) in the left berm area near the top of dam. Driftwood, etc. has gathered in an area of the reservoir which is very close to the emergency spillway inlet.

(3) Outlet Works

There were no regulated outlet works or low level drain pipes constructed for this dam.

e. Reservoir Area

The reservoir water surface elevation at the time of inspection was 837.2 feet above M.S.L.

The surface area of the reservoir at normal water level is about 15 acres. The rim appears to be stable with no severe erosional problems. The land around the reservoir slopes gently to the rim and is grass and/or tree covered. There are no homes built in close proximity to the reservoir (see Photo 12).

f. Downstream Channel

The downstream channel is not well defined and partially obstructed from the embankment to the County Highway F embankment which is located approximately 200 feet downstream of the dam (see Photos 9 and 10). Discharges through the spillways of the dam pass under the highway through the 4-foot high, 5-foot wide concrete box culvert (see Photo 11).

3.2 Evaluation

The visual inspection uncovered nothing of a consequential nature which would require immediate remedial action. However, some conditions were observed which could adversely affect the dam in the near future.

1. The possible seepage, indicated by the cattails, standing water and boggy ground at the downstream toe, could affect the structural stability of the dam. If the rate of seepage were to increase, it is possible that the seepage could transport soil particles which could

cause piping of embankment material thus leading to an eventual failure of the embankment.

2. The wave erosion on the upstream slope does not appear to affect the stability of the dam in its present condition. Nevertheless, continual erosion of the slope can only be detrimental to the stability of the dam.

3. It is unknown whether the cracks observed on the crest are indicative of shrinkage, slope movement, or foundation settlement. Due to their extent and location, the cracks were probably caused by shrinkage.

4. The rodent activity observed on the upstream slope and on the emergency spillway training berm near the embankment could jeopardize the safety of the dam. However, the large rodent burrow found on the edge of the emergency spillway could cause problems, the severity of which would depend upon the extent, activity, and direction of the burrowing. The burrows created by the animals make avenues for possible piping.

5. The surface erosion, due to the lack of protective cover in some areas of the slopes and the area to the left of the principal spillway outlet at the toe of the slope, does not appear to affect the stability of the dam in its present condition.

6. The present vegetation on the embankment should be properly maintained. A tall growth of vegetation on the embankment hinders a comprehensive inspection of the dam and potential problems could go undetected.

7. Some apparent corrosion was observed on the inside of the stand pipe of the principal spillway, and rust covered the anti-vortex device and what could be seen of the standpipe (see Photo 6). It would seem likely that the portion of the conduit within the embankment has a protective coating of the same material that was observed on the outlet

end of the pipe. However, since there was a small amount of water dripping from the outlet end, water is apparently entering the pipe through faulty seams, corroded areas, or through some other way. If from corrosion, the condition could eventually worsen to the point of allowing embankment material to be washed into the pipe.

8. In a large flood, the driftwood would drift to the inlet of the emergency spillway, possibly getting snagged in the reeds and simulating a trashrack, and contribute to the problem of rising reservoir water.

9. The discharge channel of the emergency spillway generally does not appear to be adequately protected against erosion due to flows through the spillway which could threaten the safety of the dam.

SECTION 4: OPERATIONAL PROCEDURES

4.1 Procedures

Hauck Lake Dam was built to impound water primarily for recreational purposes. There are no specific procedures which are followed for the operation of the dam.

4.2 Maintenance of Dam

The dam and appurtenant structures are maintained by the owner, Mr. Gordon K. Hauck. The dam is covered with a dense blanket of grass. The slopes are free of trees and bushes. Erosion is present at the toe of the dam near the spoil pile as explained in Section 3.1b. Some surface erosion is also present in the emergency spillway channel. The berm on the upstream slope has undergone considerable erosion due to wave action.

4.3 Maintenance of Operating Facilities

There are no operable facilities at the damsite which require any maintenance.

4.4 Description of Any Warning System in Effect

The inspection team is not aware of any warning system consisting of any electrical warning system or manual notification plans in use at the damsite.

4.5 Evaluation

Although the maintenance of Hauck Lake Dam seems to be somewhat lacking, the dam does not appear to be neglected. The remedial measures described in Section 7 should be undertaken to improve the condition of the dam.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design Data

The watershed area of the Hauck Lake Dam upstream from the dam axis is approximately 95 acres. The watershed area consists mainly of pasture and range land. Land gradients in the watershed average roughly 3 percent. The Hauck Lake Dam Reservoir is located on an unnamed tributary of Stinson Creek. The reservoir is about 0.6 miles upstream from the confluence of the unnamed tributary and Stinson Creek. At its longest arm the watershed is approximately 0.4 miles long. A drainage map showing the watershed and the downstream hazard zone is presented as Plate 1 in Appendix B.

Evaluation of the hydraulic and hydrologic features of Hauck Lake Dam was based on criteria set forth in the Corps of Engineers' "Engineer Regulation No. 1110-2-106" and additional guidance provided by the St. Louis District of the Corps of Engineers. The Probable Maximum Flood (PMF) was calculated from the Probable Maximum Precipitation (PMP) using the methods outlined in the U.S. Weather Bureau Publication, Hydrometeorological Report No. 33. The probable maximum storm duration was set at 24 hours, and storm rainfall distribution was based on criteria given in the Corps of Engineers' EM 1110-2-1411 (Standard Project Storm). The Soil Conservation Service (SCS) method was used for deriving the unit hydrograph, utilizing the Corps of Engineers' computer program HEC-1 (Dam Safety Version). The unit hydrograph parameters are presented in Appendix B. The SCS method was also used for determining the loss rate. The hydrologic soil group of the watershed was determined by use of the published soil maps. The hydrologic soil group of the watershed and the SCS curve number are presented in Appendix B. The curve number, the unit hydrograph parameters, the PMP index

rainfall and the percentages for various durations were direct input to the HEC-1 (Dam Safety Version) computer program to obtain the PMF hydrograph. The computed peak discharges of the PMF and the one-half PMF are 2,332 cfs and 1,166 cfs, respectively.

Both the PMF and the one-half PMF inflow hydrographs were routed through the reservoir by the Modified Puls Method also utilizing the HEC-1 (Dam Safety Version) computer program. A storm of 50 percent of the PMF preceded the PMF and a storm of 25 percent of the PMF preceded the one-half PMF, each by 4 days. The starting elevation for routing antecedent floods was assumed to be equal to the mean annual high water level in the reservoir. The mean annual high water level for Hauck Lake Dam Reservoir was estimated to be at the crest of the principal spillway. The water level in the reservoir at the end of the four day routing period was at the same elevation, within 0.1 feet, as the crest of the principal spillway. The reservoir was assumed at this level at the start of the routing computations for the PMF and the one-half PMF. The peak outflow discharges for the PMF and the one-half PMF are 1,526 and 296 cfs, respectively. Only the PMF when routed through the reservoir resulted in overtopping of the dam. Downstream of Hauck Lake Dam, Highway F was studied to demonstrate that the highway embankment will not be overtopped during a PMF event even in the case of the dam being overtopped, and the backwater created by the roadway culvert will not affect the discharge rating curve.

The sizes of physical features utilized to develop the stage-outflow relation for the spillway and overtopping of the dam were taken from field notes and sketches, prepared during the field inspection. The reservoir stage-capacity data were based on the U.S.G.S. Fulton, Missouri Quadrangle topographic map (7.5 minute series). The reservoir elevation-area curve and the spillway and dam overtop rating curve are presented in Plates 2 and 3, respectively, in Appendix B.

From the standpoint of dam safety, the hydrologic design of a dam must aim at avoiding overtopping. Overtopping is especially dangerous for an earth dam because of its erosive characteristics. The safe hydrologic design of an embankment dam requires a spillway discharge capability combined with an embankment height that can handle a very large and exceedingly rare flood without dam overtopping.

The Corps of Engineers designs dams to safely pass the Probable Maximum Flood that could be generated from the dam's watershed. This is the generally accepted criterion for major dams throughout the world, and is the standard for dam safety where overtopping of the dam would pose any threat to human life. Accordingly, the hydrologic requirement for safety for this dam is the capability to pass the Probable Maximum Flood without overtopping the dam.

b. Experience Data

It is believed that records of reservoir stage or spillway discharge are not maintained for this site. Nevertheless, there was no evidence of the dam ever being overtopped.

c. Visual Observations

Observations made of the spillways during the visual inspection are discussed in Section 3.1d and evaluated in Section 3.2.

d. Overtopping Potential

As indicated in Section 5.1.a, the Probable Maximum Flood when routed through the reservoir, resulted in overtopping of the dam. The peak outflow discharges for the PMF and the one-half PMF are 1,526 and 296 cfs, respectively. The capacity of the spillway just before overtopping is approximately 418 cfs. The PMF over-

topped the dam by 0.65 feet. The total duration of flow over the dam is 1 hour during the PMF. The spillway/reservoir system of Hauck Lake Dam is capable of accommodating a flood equal to approximately 60 percent of the PMF just before overtopping of the dam. The reservoir/spillway system of Hauck Lake Dam will accommodate the one-percent chance flood (100-year flood) without exceeding the top of dam.

The estimated damage zone extends approximately four miles downstream of the dam. There are six dwellings, one building, a junkyard, a shed, a school, and a park within the damage zone. Due to the particular location of the dam behind the embankment of Highway F, the downstream hazard zone could be considered safe in the event of the PMF. However, this depends upon the strength of the highway embankment since highway embankments are not designed to impound water and if the box culvert under the highway embankment is not plugged, over which Mr. Hauck has no control.

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

There were no major signs of settlement or distress observed on the embankment or foundation during the visual inspection. The possible seepage observed in the two different locations at the toe of dam could be detrimental to the stability of the embankment. Nevertheless, the possible seepage did not appear to constitute an unsafe condition at this time. It was not apparent whether the observed cracks on the top of dam were due to shrinkage, slope movement, or foundation settlement. Due to the extent and location of the cracks, the cracks were probably caused by shrinkage. The erosional problems due to wave action on the upstream berm, and due to surface runoff on the upstream slope, downstream slope, and the toe of dam to the left of the principal spillway pipe, do not endanger the structural integrity of the embankment in their present condition. Nevertheless, if the erosion continues, it can only have an adverse effect on the stability of the embankment. In the absence of seepage and stability analyses, no quantitative evaluation of the structural stability can be made.

The spillway system appeared to be structurally stable on the day of the inspection. The pipe curvature at the outlet end was seen as a defective piece of pipe, not necessarily causing any instability. It is assumed that the pipe within the embankment is not defective in this manner.

b. Design and Construction Data

Hydrologic and hydraulic analyses for this project were available and are presented in this report (see Plate 6). From the hydrologic and hydraulic computations, it appears that the dam and appurtenant structures were designed to pass a two-percent chance flood. No design computations pertaining to the embankment were uncovered during the report preparation phase. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available. No embankment or foundation soil parameters were available for carrying out a conventional stability analysis on the embankment. No construction data or specifications relating to the degree of embankment compaction were available for use in a stability analysis.

c. Operating Records

No operating records are available relating to the stability of the dam or appurtenant structures. The water level on the day of inspection was 10 inches below the crest of the principal spillway, and it is assumed that the reservoir remains close to full at all times. No regulated outlet works or low level outlets were provided for this dam.

d. Post Construction Changes

No post construction changes to the embankment are known to exist which will affect the structural stability of the dam.

e. Seismic Stability

The dam is located in Seismic Zone 1 (see Plate 9), as defined in "Recommended Guidelines for Safety Inspection of Dams" prepared by the Corps of Engineers, and will not require a seismic stability analysis. An earthquake of the magnitude which would be expected in Seismic Zone 1 will not cause significant distress to a

well designed and constructed earth dam. Available literature indicates that no active faults exist near the vicinity of the damsite.

SECTION 7: ASSESSMENT/REMEDIAL MEASURES

7.1 Dam Assessment

The assessment of the general condition of the dam is based upon available data and the visual inspection. Detailed investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation, however, the investigation is intended to identify any need for such studies.

It should be realized that the reported condition of the dam is based on observations of field conditions at the time of the inspection along with data available to the inspection team.

It is also important to realize that the condition of a dam depends upon numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be assurance that an unsafe condition would be detected.

a. Safety

The spillway capacity of Hauck Lake Dam is found to be "Inadequate". The spillway/reservoir system will accommodate about 60 percent of the PMF without overtopping the dam. The safety of the embankment will be in jeopardy if the dam is overtopped. The dam itself would be susceptible to erosion due to the high velocity of flow on its downstream slope which could lead to an eventual failure of the dam.

The dam and appurtenant structures appeared to be in fair condition. However, no quantitative evaluation of the safety of the embankment can be made in view of the absence of seepage and stability analyses. The present embankment and appurtenant structures, however, appear to have performed satisfactorily since their construction without failure or evidence of instability. There was no evidence of the dam ever having been overtopped.

The safety of the dam can be improved if the deficiencies described in Sections 3 and 6.1a are properly corrected as described in Section 7.2b.

b. Adequacy of Information

The conclusions presented in this report are primarily based upon field measurements and present condition of the dam. The two design drawings and the hydrologic and hydraulic computations were of limited use to the overall assessment of the dam and appurtenant structures. Information on the operation and maintenance of the dam was not available. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

c. Urgency

The remedial measures recommended in Paragraph 7.2 should be accomplished in the near future. The items recommended in Paragraph 7.2a should be pursued on a high priority basis.

d. Necessity for Phase II Inspection

Based upon results of the Phase I inspection, and assuming the remedial measures recommended in Paragraph 7.2 are undertaken, a Phase II inspection is not felt to be necessary.

7.2 Remedial Measures

a. Alternatives

There are several general options which may be considered to reduce the possibility of dam failure or to diminish the harmful aspects of such a failure. Some of these options are:

1. Increase the spillway capacity to pass the PMF without overtopping the dam.
2. Increase the height of the dam enough to pass the PMF without overtopping the dam; an investigation should be done which also includes studying the effects on the structural stability of the existing embankment. The overtopping depth during the occurrence of the PMF, stated in Section 5.1d, is not the required or recommended increase in the height of the dam.
3. A combination of 1 and 2 above.


b. O & M Procedures

1. The possible seepage at the downstream toe should be monitored to detect any changes in turbidity, location or quantity. Any changes should be investigated further by a qualified engineer and repairs made as necessary.
2. The erosion due to wave action on the upstream berm should be properly repaired and protected from further damage.
3. The observed cracking on the top of dam should be monitored to ensure that it is not symptomatic of distress in the slopes or foundation. Large cracks should be properly repaired


4. Determine the extent of damage done to the embankment by burrowing animals, if any, and make corrective repairs as required. All burrowing animals should be eliminated from the embankment and their burrows properly backfilled and compacted.
5. The areas on the embankment, where the vegetation is sparse and erosion due to surface runoff has occurred, should be properly repaired and then adequately protected from surface erosion by a good vegetative cover.
6. The vegetation on the embankment should be maintained periodically and large vegetation, such as bushes and trees, should be prevented from growing on the slope.
7. The driftwood, etc. in the reservoir, especially in the vicinity of the emergency spillway inlet, should be removed from the reservoir and the discharge channel of the emergency spillway (especially near the crest of the spillway) should be adequately protected to prevent excessive erosion due to flows through the spillway.
8. The functioning of the principal spillway system should be monitored in order to determine the severity and progression of the leaks, if any, in the conduit system.
9. Seepage and stability analyses should be performed by a professional engineer experienced in the design and construction of earth dams.
10. The owner should initiate the following programs:
 - (a) Periodic inspection of the dam by a professional engineer experienced in the design and construction of earth dams.

- (b) Set up a maintenance schedule and log all visits to the dam for operation, repairs and maintenance.


PLATES




LOCATION MAP - HAUCK LAKE DAM



HAUCK LAKE DAM (MO. 10989)
PLAN AND ELEVATION
(SHEET 1 OF 2)




SECTION A-A
MAXIMUM SECTION



SECTION B-B
EMERGENCY SPILLWAY PROFILE

① REFERENCE POINT SHEET 1 OF 2


HAUCK LAKE DAM (MO. 10989)
MAXIMUM SECTION OF EMBANKMENT AND
EMERGENCY SPILLWAY PROFILE
(SHEET 2 OF 2)




ANTI-SEEP COLLAR

Notes:

1. All welds shall be watertight except angle iron connections
2. All pipe and steel plates shall have minimum thickness of 0.179"



Top View



SECTION ALONG Q-Q OF INLET

INLET SECTION

Not to Scale

COOPERATOR <u>G. Hawick</u>	SEC. <u>T. A.</u>
COOPERATING WITH <u>STATE</u>	DATE <u>10-13</u>
COUNTY <u>STATE</u>	
SURVEYED <u>DATE</u>	
DETAILS FOR WELDED STEEL PIPE DROP INLET SPILLWAY	
U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	
Designed by <u>DATE</u>	Approved by <u>DATE</u>
Drawn <u>DATE</u>	Checked <u>DATE</u>
Traced <u>DATE</u>	Checked <u>DATE</u>

FILED

DESIGN SHEET
33 REV 5-58

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

CP-1112-11-61

PROJECT <u>Barren Creek</u>		DATE <u>11-1-76</u>		JOB NO. <u>11-78</u>
BY <u>WJ</u>	DATE <u>11-1-76</u>	CHECKED BY	DATE	
SUBJECT <u>Design of DC</u>				SHEET <u> </u> OF <u> </u>

ADD 65 Acres

$Q = 1.75 \times \frac{1}{2} \times \frac{1}{1} \times \frac{1}{2} \times \frac{1}{2} \times \frac{1}{2} \times \frac{1}{2} \times \frac{1}{2} \times \frac{1}{2} = 1.75 \text{ cfs Val } 1.1$

$Q = 1.75 \text{ cfs} \quad V_r = 65 \times 2.67 = 1.8 \text{ Ac. ft.}$

$Q = 1.75 \text{ cfs} \quad V_r = 65 \times 2.62 = 1.70 \text{ Ac. ft.}$

$\frac{1.75}{10} \text{ MSP} \quad L = 80' \quad R = 20' \quad Q = 1.3 \text{ cfs Outlet El. } 11.2$
 65.7

$Q = 1.75 \text{ cfs} \quad V_r = 65 \times 2.67 = 1.8 \text{ Ac. ft.}$
 $193 \quad 13.7$

DESIGN OF SPILLWAY $d = 2.5' \quad B = 12' \quad C = 1.0'$



$V_r = 1.75 \text{ cfs} \quad \text{pos. type} \quad Q = 0.3 \times 240 = 7 \text{ cfs}$

11.2 ft. above

18.0 / 17 1.94

CB 9-20-74

dam relocation



⊕ LOCATION OF DAM

NOTE: LEGEND OF THIS DAM IS ON PLATE 8


REFERENCE

GEOLOGIC MAP OF MISSOURI
DEPARTMENT OF NATURAL RESOURCES
MISSOURI GEOLOGICAL SURVEY
KENNETH H. ANDERSON, 1979

REGIONAL GEOLOGICAL MAP
OF
HAUCK LAKE DAM

LEGEND

<u>PERIOD</u>	<u>SYMBOL</u>	<u>DESCRIPTION</u>
QUATERNARY	Qal	ALLUVIUM: SAND, SILT, GRAVEL
PENNSYLVANIAN	{ Pu	PENNSYLVANIAN UNDIFFERENTIATED
	{ Pm	MARMATON GROUP: CYCLIC DEPOSITS OF SHALE, LIMESTONE AND SANDSTONE
	{ Pcc	CHEROKEE GROUP: CYCLIC DEPOSITS OF SHALE, LIMESTONE AND SANDSTONE
MISSISSIPPIAN	{ Mo	KEOKUK - BURLINGTON FORMATION: CHERTY GRAYISH BROWN SANDY LIMESTONE
	{ Mk	CHOUTEAU GROUP: NORTHVIEW, COMPTON AND BACHELOR FORMATION (LIMESTONE AND SHALE
DEVONIAN	D	SULPHUR SPRING GROUP: BUSHBERG SANDSTONE, GLEN PARK LIMESTONE, GRASSY CREEK SHALE
ORDOVICIAN	{ Ou	MAQUOKETA SHALE, KIMMSWICK LIMESTONE
	{ Osp	ST PETER SANDSTONE
	{ Ojc	SMITHVILLE FORMATION, POWELL DOLOMITE
	{ Or	ROUBIDOUX FORMATION: LIMESTONE AND SANDSTONE



APPENDIX A

PHOTOGRAPHS TAKEN DURING INSPECTION




PHOTO INDEX
FOR
HAUCK LAKE DAM

Hauck Lake Dam
Photographs

- Photo 1 - View of the upstream slope showing uneven berm and tall grass slope protection.
- Photo 2 - View of the top of dam showing tall stand of grass.
- Photo 3 - View of the downstream slope showing tall grasses, toe of slope, and emergency spillway discharge channel berm.
- Photo 4 - View of the principal spillway outlet and discharge pool showing large bare area and scarp along the toe.
- Photo 5 - Burrow found on the berm on the left side of the emergency spillway near the dam embankment.
- Photo 6 - View of the principal spillway showing anti-vortex device, rust condition, reeds around inlet, and low water level.
- Photo 7 - View of the principal spillway outlet showing discharge pool, end pipe curvature, and lack of grass cover protection.
- Photo 8 - Crest of emergency spillway looking towards reservoir showing sparseness of grass cover, and reeds at inlet area.
- Photo 9 - Photo shows the dam embankment on left, highway embankment on right, bare spot in center, and emergency spillway discharge channel in foreground.
- Photo 10 - Principal spillway outlet showing discharge pool, erosion flow, downstream channel and concrete box culvert under highway.

- Photo 11 - Close-up view of reinforced concrete box culvert (5 feet wide by 4 feet high) under highway embankment adjacent dam embankment.
- Photo 12 - View of the reservoir and rim.
- Photo 13 - View of the downstream hazard located approximately 0.2 miles downstream of the dam.
- Photo 14 - View of the downstream hazard located approximately 0.2 miles downstream of the dam.

Hauck Lake Dam



Photo 1



Photo 2

Hauck Lake Dam



Photo 3



Photo 4

Hauck Lake Dam




Photo 5




Photo 6

Hauck Lake Dam



Photo 7



Photo 8

Hauck Lake Dam



Photo 9



Photo 10

Hauck Lake Dam



Photo 11



Photo 12

Hauck Lake Dam



Photo 13



Photo 14

APPENDIX B

HYDROLOGIC AND HYDRAULIC COMPUTATIONS



PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION - MISSOURI

SHEET NO. _____ OF _____

DAM NAME: HAUCK LAKE DAM / ID NO.: 10989

JOB NO. 1263


RESERVOIR ELEVATION - AREA DATA

BY FL DATE JUNE 80

KLB✓

ELEV. (M.S.L.) (Ft.)	RESERVOIR SURFACE AREA (Acres)	REMARKS
820	0	Assumed bottom.
823	1	Measured on USGS Quad.
830	6	Interpolated.
838	15	" , Principal Spillway
839.4	17	" , Emergency Spillway.
840	18	Measured on USGS Quad
842	21	Interpolated , Top of dam (Assumed)
850	35	"
860	57	Measured on USGS Quad.

PLATE 2, APPENDIX B



HAUCK LAKE DAM (MC. 10989)
RESERVOIR ELEVATION-AREA CURVE

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. _____ OF _____

DAM NAME: HAUCK LAKE DAM

JOB NO. 1263

UNIT HYDROGRAPH PARAMETERS

BY FE DATE JUNE 10

- 1) DRAINAGE AREA, $A = 0.148$ sq. mi. = (95 acres)
- 2) LENGTH OF STREAM, $L = (0.5' \times 2000' = 1000') = 0.189$ mi.
- 3) ELEVATION AT DRAINAGE DIVIDE ALONG THE LONGEST STREAM,
 $H_1 = 865$
- 4) ELEVATION OF RESERVOIR AT SPILLWAY CREST, $H_2 = 838$
- 5) ELEVATION OF CHANNEL BED AT $0.85L$, $E_{85} = 863$
- 6) ELEVATION OF CHANNEL BED AT $0.10L$, $E_{10} = 840$
- 7) AVERAGE SLOPE OF THE CHANNEL, $S_{AVG} = (E_{85} - E_{10}) / 0.75L = 0.03$
- 8) TIME OF CONCENTRATION:

A) BY KIRPICH'S EQUATION,

$$t_c = [(11.9 \times L^3) / (H_1 - H_2)]^{0.385} = \left(\frac{11.9 \times 0.189^3}{865 - 838} \right)^{0.385} = 0.11$$

B) BY VELOCITY ESTIMATE,

$$SLOPE = 3\% \Rightarrow AVG. VELOCITY = 3 \text{ fps}$$

$$t_c = L/V = \frac{1000}{3} \times \frac{1}{3600} = 0.09 \text{ hr.}$$

USE $t_c = 0.11$

9) LAG TIME, $t_L = 0.6 t_c = 0.064$

10) UNIT DURATION, $D \leq t_L / 3 = 0.021$

< 0.083 hr.

USE $D = 0.083$

11) TIME TO PEAK, $T_p = D/2 + t_L = 0.106$

12) PEAK DISCHARGE,

$$q_p = (484 \times A) / T_p = \frac{484 \times 0.148}{0.106} = 680 \text{ cfs}$$

PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION / MISSOURI - 1980 SHEET NO. _____ OF _____
 DAM NAME: HAUCK LAKE DAM JOB NO. 1263
 CURVE NUMBER DETERMINATION BY FL DATE JUNE 80

I) SOIL GROUP

WATERSHED SOILS IN THE BASIN CONSIST OF GROUP

WELLER, KESWICK, LINDLEY, MANDEVILLE

A.
 B.
 C.
 D.

GROUP C SOILS SEEM TO PREDOMINATE THE BASIN. THEREFORE,
 ASSUME GROUP C SOILS FOR THE ENTIRE WATERSHED
 FOR HYDROLOGIC PURPOSES.

II) COVER COMPLEX

ASSUMED LAND USE	ASSUMED HYDROLOGIC CONDITION	PER CENT AREA	CN (AMC II)
<u>RANGE</u>	<u>FAIR</u>	<u>100</u>	<u>79</u>

III) CURVE NUMBER

WEIGHTED AVERAGE CN = 79 FOR AMC II

CURVE NUMBER = 91 FOR AMC III

PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. _____ OF _____

DAM NAME: HAUCK LAKE DAM

JOB NO. 1263

PROBABLE MAXIMUM PRECIPITATION

BY FL DATE JUNE 60

DETERMINATION OF PMP

1) Determine drainage area of the basin

$$D.A. = 45 A_c = 0.15 \text{ sq mi}$$

2) Determine PMP Index Rainfall (for D.A. = 200 sq. mi. & 24 hr. duration)

Location of centroid of basin,

$$\text{Long.} = 91^{\circ} 58' 52''$$


$$\text{Lat.} = 38^{\circ} 51' 05''$$

$$\text{PMP} = 24.9 \text{ (from Fig. 1, HMR 33)}$$

$$\text{Zone} = 7$$

3) Determine basin rainfall in terms of percentage of PMP Index Rainfall for various durations.
(from Fig. 2, HMR 33)

Duration (Hrs.)	Percent of Index Rainfall (%)	Total Rainfall (Inches)	Rainfall Increments (Inches)	Duration of Increment (Hrs.)
6	100	24.9	24.9	6
12	120	29.9	5	6
24	130	32.4	2.5	12



⊕ Location of Basin Centroid

Havuck Lake Dam (Mo. 10982)




FIGURE 2
SEASONAL VARIATION
DEPTH-AREA-DURATION RELATIONSHIPS
Percentage to be applied to 200 square miles
24 hour probable maximum precipitation values
for: THE-ALL SEASON ENVELOPE

SHEET NO. _____ OF _____

DAM SAFETY INSPECTION

JOB NO. 1263

HAUCK LAKE DAM

10989

BY FZ DATE JUNE 80SERVICE Spillway =

- WEIR FLOW :

$$Q = CL H^{3/2}$$

$$C = 3.3$$

$$L = \frac{81}{12} \times \pi = 5.5$$

$$H = WSEL - 838$$

$$\Rightarrow Q = 18.14 H^{3/2}$$

- PRESSURE FLOW

$$K_{entrance} = 0.5$$

$$K_{exit} = 1.0$$

$$K_{bend + contraction} = 0.5$$

$$K_{friction} = \frac{29.1 n^2 L}{R^{4/3}}$$

$$n = 0.012$$

$$R = \frac{D}{4}$$

$$21" \phi \Rightarrow K_f = \left(\frac{10.5}{21} \right)^2 \frac{29.1 \times 0.012^2 \times 10}{(1.75/4)^{4/3}} = 0.03$$

$$10.5" \phi \Rightarrow K_f = \frac{29.1 \times 0.012^2 \times 91}{(0.875/4)^{4/3}} = 2.89$$

$$Q = A \sqrt{\frac{2gH}{K}}$$

$$K = 1 + 0.5 \times 0.5 + 0.03 + 2.89 = 4.92$$

$$H = WSEL - 817 + \frac{10.5}{12} \times \frac{1}{2} = WSEL - 817.44$$

$$A = 0.6$$

$$\Rightarrow Q = 2.17 \sqrt{H}$$

- Check for orifice flow :

$$Q = 0.6 A \sqrt{2gH}$$

$$H = WSEL - 838$$

$$Q = 0.6 \left(\frac{21}{12} \right)^2 \times \frac{\pi}{4} \sqrt{2gH} = 11.6 \sqrt{H}$$



Lower pipe

$$H = WSEL - 828.4$$

$$\Rightarrow Q = 0.6 \left(\frac{10.5}{12} \right)^2 \times \frac{\pi}{4} \sqrt{2gH} = 2.9 \sqrt{H}$$


does not control

→ see graph.




DAM SAFETY INSPECTION
HAUCK LAKE DAM

SHEET NO. OF
JOB NO. 1203
BY RE DATE JUNE 80




① *				② *				WSEC		③		④		Total
y_{c1}	A_1	T_1	V_1	Q_1	y_2	A_2	T_2	V_2	$V_{2/3}$	H_2	H_3	C_3	Q_4	Discharge
0.50	13.1	21.2	3.8	50	0.85	24.1	33.5	2.1	.07	0.92	838.00		0	0
0.99	27.0	35.2	5.2	150	1.47	47.2	41.1	3.2	.16	1.62	838.74		10.0	10.0
1.51	48.8	41.6	6.2	300	2.06	73.5	48.4	4.1	.26	2.32	839.40		10.4	10.0
1.78	60.5	44.9	6.6	400	2.37	89.2	52.2	4.5	.31	2.68	841.72		10.5	60.
2.02	71.6	47.9	7.0	500	2.64	104.0	55.0	4.8	.36	3.00	842.08	2.90	10.7	161.
2.24	82.4	50.6	7.3	600	2.87	116.7	"	5.1	.41	3.28	842.40	3.04	10.8	311.
2.62	102.8	55.0	7.8	800	3.26	137.6	"	5.8	.52	3.78	842.68	3.03	10.9	449
2.92	119.2	55.0	8.4	1000	3.60	156.4	"	6.4	.63	4.24	843.18	3.04	11.0	950
3.19	134.1	55.0	9.0	1200	3.92	173.9	"	6.9	.74	4.66	843.64	3.04	11.1	1590.
3.47	149.0	55.0	9.4	1400	4.22	190.1	"	7.4	.84	5.06	844.06	3.05	11.2	3055.
											844.46	3.05	11.3	4689
												3.05		6405
														8189

③ $Q_3 = C_3 L_3 H_3^{3/2}$
 $L_3 = 576$
 $H_3 = H_2 - 2.6$




* See results of HEC2

PLATE 3, APPENDIX B



HAUCK LAKE DAM (MO. 10989)
SPILLWAY & OVERTOP RATING CURVE



HWY. "F" D/S OF HAUCK LAKE DAM
RESERVOIR AREA CURVE

PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. _____ OF _____

DAM NAME: HWY "F" D/S

JOB NO. 1263

UNIT HYDROGRAPH PARAMETERS

BY FE DATE JUNE 80

- 1) DRAINAGE AREA, $A = 0.008$ sq. mi. = (5 acres)
- 2) LENGTH OF STREAM, $L = (0.35' \times 2000' = 700') = 0.133$ mi.
- 3) ELEVATION AT DRAINAGE DIVIDE ALONG THE LONGEST STREAM,
 $H_1 = 850$
- 4) ELEVATION OF RESERVOIR AT SPILLWAY CREST, $H_2 = 815$
- 5) ELEVATION OF CHANNEL BED AT $0.85L$, $E_{85} = 845$
- 6) ELEVATION OF CHANNEL BED AT $0.10L$, $E_{10} = 818$
- 7) AVERAGE SLOPE OF THE CHANNEL, $S_{AVG} = (E_{85} - E_{10}) / 0.75L = 0.05$
- 8) TIME OF CONCENTRATION:

A) BY KIRPICH'S EQUATION,

$$t_c = [(11.9 \times L^3) / (H_1 - H_2)]^{0.385} = \left(\frac{11.9 \times 0.133^3}{850 - 815} \right)^{0.385} = 0.064$$

B) BY VELOCITY ESTIMATE,

$$\text{SLOPE} = 5\% \Rightarrow \text{AVG. VELOCITY} = 4 \text{ fps.}$$

$$t_c = L/V = \frac{700}{4} \times \frac{1}{3600} = 0.05$$

$$\text{USE } t_c = 0.064 \text{ hr}$$

$$9) \text{ LAG TIME, } t_L = 0.6 t_c = 0.039 \text{ hr}$$

$$10) \text{ UNIT DURATION, } D \leq t_L / 3 = 0.013 \text{ hr}$$

$$< 0.083 \text{ hr.}$$

$$\text{USE } D = 0.083 \text{ hr.}$$

$$11) \text{ TIME TO PEAK, } T_p = D/2 + t_L = 0.08 \text{ hr}$$

12) PEAK DISCHARGE,

$$q_p = (484 \times A) / T_p = 48 \text{ cfs.}$$

PRC ENGINEERING CONSULTANTS, INC.


SHEET NO. _____ OF _____

DAM SAFETY INSPECTION

JOB NO. 1263

HWY "F" D/S OF HAUCK LAKE DAM

BY FE DATE JUNE 80



LOW FLOW

$S = 0.029$
 $n = 0.015$

$A = 54$
 $P = 5 + 2y$

$$Q = \frac{1.49}{n} \times 54 \times \frac{A^{5/3}}{P^{2/3}}$$

y_N	Q	y_c	Regime
1	67	1.77	Supercritical.
2	180	3.43	"
3	310	4.92	"

} \Rightarrow Control at inlet at critical depth.

Then

$$y_c = \frac{2}{3} H \quad H = WSEL - 815$$

$$\text{and } Q = 5 \sqrt{y_c^3 g} = 15.444 \sqrt{H^3}$$

4E 1307

WDEL

810

300 ft 822.7

Pressure Point

Low flow

100

PRC ENGINEERING CONSULTANTS, INC.

SHEET NO. _____ OF _____

DAM SAFETY INSPECTION

JOB NO. 1263

HWY "F" D/S OF HAUCK LAKE DAM

BY FE DATE JUNE 80

PRESSURE FLOW

$$K_{entrance} = 0.5$$

$$K_{exit} = 1.0$$

$$K_{friction} = \frac{29.1 n^2 L}{R^{4/3}} = \frac{29.1 \times 0.015^2 \times 140}{\left(\frac{20}{18}\right)^{4/3}} = 0.8$$

$$Q = A \sqrt{\frac{2gH}{K_T}}$$

$$K_T = 2.3$$

$$H = WSEL - 813$$

$$Q = 105.8 \sqrt{H}$$

WEIR FLOW OVER THE HWY

$$Q = CLH^{3/2}$$

$$L = 1000'$$

$$H = WSEL - 842$$

WSEL	5x4 RCB		WEIR			Total Q
	H	Q	H	C	Q	
815	0	0				0
817	2	44				44
819	4	124				124
822.7	9.1	330				330
832	19	461				461
842	29	570	0			570
852.2	24.2	572	0.2	2.97	266	838
864	29.4	574	0.4	3.01	762	1336
874.7	29.6	576	0.6	3.03	1408	1984
884.8	29.8	578	0.8	3.03	2168	2746
895	30	579	1.0	3.03	3030	3609
905.2	30.2	581	1.2	3.04	3996	4577

PRC ENGINEERING CONSULTANTS, INC.

DAM SHEET INSPECTION / MISSOURI - 1980

SHEET NO. _____ OF _____


HAUCK LAKE DAM (MO. 10989)

JOB NO. 1263

CHANNEL CAPACITY D/S OF HWY 'F' EMBANKMENT

BY JFK

DATE 9/17/80



AVERAGE CHANNEL CROSS SECTION

$$S_{Avg} = 0.03$$


$$Q = \frac{1.49}{n} A R^{2/3} S^{1/2}$$

$$Q = \frac{1.49}{0.04} (75) (3.11)^{2/3} (0.03)^{1/2}$$

$$Q = 1,030 \text{ cfs}$$

∴ Since the maximum discharge through the culvert is approximately 600 cfs, the D/S channel should be able to carry the flow without causing any tailwater affects at the culvert outlet.

PLATE 5, APPENDIX B




HWY. "F" D/S OF HAUCK LAKE DAM
OVERTOP AND CULVERT RATING CURVE

Stage	S	Q	ΔE	$\Sigma \Delta E$
839.8	135	22		1
.6	133	15	0.05	1.05
.4	131	10	0.08	1.14
.2	129	10	0.10	1.24
839.0	127	10	0.10	1.34
.8	124	10	0.15	1.49
.7	123	10	0.05	1.54
.5	120	6.5	0.18	1.72
.3	116	3.5	0.40	2.13
.2	113	2	0.55	2.68
.1	110	1	1.01	3.68
838.0	104	0	6.05	9.73


WATER LOSS DUE TO

$$\Delta E = 2(3 - 2.13) = 0.14$$

within the time $\frac{1}{10}$ of the stage
 from back to ELEV 135 in
 four days after the G.P.F.



Stage	S	Q	At	ΣAt
4	0.35	27	0.	1.0
2	0.3	22	0.	1.0
816.0	0.25	18	0.	1.0
815.8	0.20	14	0.	1.0
6	0.15	10	0.	1.01
4	0.1	6	0.	1.01
2				
815.0	0	0	0.02	1.03



PRC ENGINEERING CONSULTANTS, INC.

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF 1

DAM NAME: HWY "F", HAUCK LAKE DAM BREACHED

JOB NO. 1263

UNIT HYDROGRAPH PARAMETERS

BY _____ DATE _____

- 1) DRAINAGE AREA, $A = 0.156$ sq. mi. = (acres)
- 2) LENGTH OF STREAM, $L = (' \times ' = 2300 ') = 0.436$ mi.
- 3) ELEVATION AT DRAINAGE DIVIDE ALONG THE LONGEST STREAM,
 $H_1 = 865$
- 4) ELEVATION OF RESERVOIR AT SPILLWAY CREST, $H_2 = 815$
- 5) ELEVATION OF CHANNEL BED AT $0.85L$, $E_{85} = 860$
- 6) ELEVATION OF CHANNEL BED AT $0.10L$, $E_{10} = 825$
- 7) AVERAGE SLOPE OF THE CHANNEL, $S_{AVG} = (E_{85} - E_{10}) / 0.75L = 0.02$
- 8) TIME OF CONCENTRATION:

A) BY KIRPICH'S EQUATION,

$$t_c = [(11.9 \times L^3) / (H_1 - H_2)]^{0.385} = \left(\frac{11.9 \times 0.436^3}{865 - 815} \right)^{0.385} = 0.22 \text{ hr}$$

B) BY VELOCITY ESTIMATE,

$$SLOPE = 2\% \Rightarrow \text{AVG. VELOCITY} = 2.5 \text{ fps}$$

$$t_c = L / V = 0.25 \text{ hr}$$

$$\text{USE } t_c = 0.22 \text{ hr}$$

$$9) \text{ LAG TIME, } t_l = 0.6 t_c = 0.132$$

$$10) \text{ UNIT DURATION, } D \leq t_l / 3 = 0.044$$

$$< 0.083 \text{ hr.}$$

$$\text{USE } D = 0.083$$

$$11) \text{ TIME TO PEAK, } T_p = D/2 + t_l = 0.174$$

12) PEAK DISCHARGE,

$$q_p = (484 \times A) / T_p = 435 \text{ cfs}$$

PRC ENGINEERING CONSULTANTS, INC.

SHEET INSPECTION / MISSOURI - 1980


SHEET NO. 1 OF 1

HAUCK LAKE DAM (MO. 10989)

JOB NO. 1263

BREACH PARAMETERS FOR HAUCK LAKE DAM

BY JFK DATE 9/16/80



CAPACITY AT TOP OF DAM = 21 ac-ft

 $0.15 \times 21 = 3.15 \text{ ac-ft}$

HEC1DB INPUT DATA

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1974
 LAST MODIFICATION 26 FEB 75

DAM SAFETY INSPECTION - MISSOURI									
HAUCK LAKE DAM MO.10953									
PMF AND HALF PMF									
A1	300	0	5	0	0	0	0	0	0
A2	5								
A3	1	2	1						
A4	1	.5							
A5		DAM							
A6									
A7									
A8									
A9									
A10									
A11	1	2	.148	.148	1				1
A12		24.9	100	120					
A13									
A14		.064							
A15			1						
A16	1	DAM							
A17									
A18									
A19	1								
A20	838	838.74	839.40	840.32	841.02	841.72	842.08	842.40	843.13
A21	843.54	844.06	844.46						
A22	0	10	10	60	161	311	449	950	1590
A23	4689	6405	8189						
A24	0	1	6	15	17	18	21	35	57
A25	420	523	830	838	839.4	840	842	850	860
A26	838								
A27	542								

(CONTINUED)

NO	DATE	DESCRIPTION	AMOUNT	BALANCE
1	1/1	INITIAL DEPOSIT	100.00	100.00
2	1/15	PAYROLL	25.00	75.00
3	1/20	RENT	15.00	60.00
4	1/25	FOOD	10.00	50.00
5	1/30	UTILITIES	5.00	45.00
6	2/5	SALARY	120.00	165.00
7	2/10	RENT	15.00	150.00
8	2/15	FOOD	10.00	140.00
9	2/20	UTILITIES	5.00	135.00
10	2/25	SALARY	120.00	255.00
11	2/28	RENT	15.00	240.00
12	3/5	FOOD	10.00	230.00
13	3/10	UTILITIES	5.00	225.00
14	3/15	SALARY	120.00	345.00
15	3/20	RENT	15.00	330.00
16	3/25	FOOD	10.00	320.00
17	3/30	UTILITIES	5.00	315.00
18	4/5	SALARY	120.00	435.00
19	4/10	RENT	15.00	420.00
20	4/15	FOOD	10.00	410.00
21	4/20	UTILITIES	5.00	405.00
22	4/25	SALARY	120.00	525.00
23	4/30	RENT	15.00	510.00
24	5/5	FOOD	10.00	500.00
25	5/10	UTILITIES	5.00	495.00
26	5/15	SALARY	120.00	615.00
27	5/20	RENT	15.00	600.00
28	5/25	FOOD	10.00	590.00
29	5/30	UTILITIES	5.00	585.00
30	6/5	SALARY	120.00	705.00
31	6/10	RENT	15.00	690.00
32	6/15	FOOD	10.00	680.00
33	6/20	UTILITIES	5.00	675.00
34	6/25	SALARY	120.00	795.00
35	6/30	RENT	15.00	780.00
36	7/5	FOOD	10.00	770.00
37	7/10	UTILITIES	5.00	765.00
38	7/15	SALARY	120.00	885.00
39	7/20	RENT	15.00	870.00
40	7/25	FOOD	10.00	860.00
41	7/30	UTILITIES	5.00	855.00
42	8/5	SALARY	120.00	975.00
43	8/10	RENT	15.00	960.00
44	8/15	FOOD	10.00	950.00
45	8/20	UTILITIES	5.00	945.00
46	8/25	SALARY	120.00	1065.00
47	8/30	RENT	15.00	1050.00
48	9/5	FOOD	10.00	1040.00
49	9/10	UTILITIES	5.00	1035.00
50	9/15	SALARY	120.00	1155.00
51	9/20	RENT	15.00	1140.00
52	9/25	FOOD	10.00	1130.00
53	9/30	UTILITIES	5.00	1125.00
54	10/5	SALARY	120.00	1245.00
55	10/10	RENT	15.00	1230.00
56	10/15	FOOD	10.00	1220.00
57	10/20	UTILITIES	5.00	1215.00
58	10/25	SALARY	120.00	1335.00
59	10/30	RENT	15.00	1320.00
60	11/5	FOOD	10.00	1310.00
61	11/10	UTILITIES	5.00	1305.00
62	11/15	SALARY	120.00	1425.00
63	11/20	RENT	15.00	1410.00
64	11/25	FOOD	10.00	1400.00
65	11/30	UTILITIES	5.00	1395.00
66	12/5	SALARY	120.00	1515.00
67	12/10	RENT	15.00	1500.00
68	12/15	FOOD	10.00	1490.00
69	12/20	UTILITIES	5.00	1485.00
70	12/25	SALARY	120.00	1605.00
71	12/30	RENT	15.00	1590.00
72	1/5	FOOD	10.00	

INFLOW PMF AND ONE-HALF PMF HYDROGRAPHS


AD-A104 997

PRC CONSOER TOWNSEND INC ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM. HAUCK LAKE DAM (MO. 10989); MISSOURI-ETC(U)
SEP 80 W 6 SHIFRIN
DACW43-88-C-0094
NL

F/G 13/13

UNCLASSIFIED

2 of 2
AD-A104-997



END
DATE
FILMED
10-81
DTIC

PRINTED BY SOURCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT
ROUTE HYDROGRAPH TO
ROUTE HYDROGRAPH AT
COMBIN. 2 HYDROGRAPHS AT
ROUTE HYDROGRAPH TO
END OF NETWORK

QAM
QAM
HMY
HMY
HMY

NO. 547-50710.
TIME 40.35.17.

NO	NHR	MMIN	IDAY	IMH	IMIN	METPC	IMLT	IPRT	INSTAN
300	0	5	0	0	0	0	0	0	0
JOB SPECIFICATION									
			JOPER	NUT	LOOPT	TRACE			
			5	0	0	0			

ratios = 1.00, .50

THE FOUNDER-ELEMENTATIONS FOR THE MAIN CHAINAGE ARE:

	HYDROGRAPH DATA	RATIO	ISAM	LOCAL
DATE	0.00	0.00	0.00	0.00
TIME	0.00	0.00	0.00	0.00
STATION	0.00	0.00	0.00	0.00
INSPC	0.00	0.00	0.00	0.00

DATE	DESCRIPTION	AMOUNT	BALANCE
1996-01-01	Opening Balance		100.00
1996-01-15	Deposit	50.00	150.00
1996-02-01	Withdrawal	25.00	125.00
1996-02-15	Deposit	75.00	200.00
1996-03-01	Withdrawal	30.00	170.00
1996-03-15	Deposit	60.00	230.00
1996-04-01	Withdrawal	40.00	190.00
1996-04-15	Deposit	80.00	270.00
1996-05-01	Withdrawal	50.00	220.00
1996-05-15	Deposit	90.00	310.00
1996-06-01	Withdrawal	60.00	250.00
1996-06-15	Deposit	100.00	350.00
1996-07-01	Withdrawal	70.00	280.00
1996-07-15	Deposit	110.00	390.00
1996-08-01	Withdrawal	80.00	310.00
1996-08-15	Deposit	120.00	430.00
1996-09-01	Withdrawal	90.00	340.00
1996-09-15	Deposit	130.00	470.00
1996-10-01	Withdrawal	100.00	370.00
1996-10-15	Deposit	140.00	510.00
1996-11-01	Withdrawal	110.00	400.00
1996-11-15	Deposit	150.00	550.00
1996-12-01	Withdrawal	120.00	430.00
1996-12-15	Deposit	160.00	590.00
1997-01-01	Withdrawal	130.00	460.00
1997-01-15	Deposit	170.00	630.00
1997-02-01	Withdrawal	140.00	490.00
1997-02-15	Deposit	180.00	670.00
1997-03-01	Withdrawal	150.00	520.00
1997-03-15	Deposit	190.00	710.00
1997-04-01	Withdrawal	160.00	550.00
1997-04-15	Deposit	200.00	750.00
1997-05-01	Withdrawal	170.00	580.00
1997-05-15	Deposit	210.00	790.00
1997-06-01	Withdrawal	180.00	610.00
1997-06-15	Deposit	220.00	830.00
1997-07-01	Withdrawal	190.00	640.00
1997-07-15	Deposit	230.00	870.00
1997-08-01	Withdrawal	200.00	670.00
1997-08-15	Deposit	240.00	910.00
1997-09-01	Withdrawal	210.00	700.00
1997-09-15	Deposit	250.00	950.00
1997-10-01	Withdrawal	220.00	730.00
1997-10-15	Deposit	260.00	990.00
1997-11-01	Withdrawal	230.00	760.00
1997-11-15	Deposit	270.00	1030.00
1997-12-01	Withdrawal	240.00	790.00
1997-12-15	Deposit	280.00	1070.00
1998-01-01	Withdrawal	250.00	820.00
1998-01-15	Deposit	290.00	1110.00
1998-02-01	Withdrawal	260.00	850.00
1998-02-15	Deposit	300.00	1150.00
1998-03-01	Withdrawal	270.00	880.00
1998-03-15	Deposit	310.00	1190.00
1998-04-01	Withdrawal	280.00	910.00
1998-04-15	Deposit	320.00	1230.00
1998-05-01	Withdrawal	290.00	940.00
1998-05-15	Deposit	330.00	1270.00
1998-06-01	Withdrawal	300.00	970.00
1998-06-15	Deposit	340.00	1310.00
1998-07-01	Withdrawal	310.00	1000.00
1998-07-15	Deposit	350.00	1350.00
1998-08-01	Withdrawal	320.00	1030.00
1998-08-15	Deposit	360.00	1390.00
1998-09-01	Withdrawal	330.00	1060.00
1998-09-15	Deposit	370.00	1430.00
1998-10-01	Withdrawal	340.00	1090.00
1998-10-15	Deposit	380.00	1470.00
1998-11-01	Withdrawal	350.00	1120.00
1998-11-15	Deposit	390.00	1510.00
1998-12-01	Withdrawal	360.00	1150.00
1998-12-15	Deposit	400.00	1550.00
1999-01-01	Withdrawal	370.00	1180.00
1999-01-15	Deposit	410.00	1590.00
199			

OFFER CH E 93.00

RECEIVED

三、

DATE	DESCRIPTION	AMOUNT	BALANCE
1964-12-31	ADAMS, LAG	0.00	0.00
1965-01-01			0.00
1965-01-02			0.00
1965-01-03			0.00
1965-01-04			0.00
1965-01-05			0.00
1965-01-06			0.00
1965-01-07			0.00
1965-01-08			0.00
1965-01-09			0.00
1965-01-10			0.00
1965-01-11			0.00
1965-01-12			0.00
1965-01-13			0.00
1965-01-14			0.00
1965-01-15			0.00
1965-01-16			0.00
1965-01-17			0.00
1965-01-18			0.00
1965-01-19			0.00
1965-01-20			0.00
1965-01-21			0.00
1965-01-22			0.00
1965-01-23			0.00
1965-01-24			0.00
1965-01-25			0.00
1965-01-26			0.00
1965-01-27			0.00
1965-01-28			0.00
1965-01-29			0.00
1965-01-30			0.00
1965-01-31			0.00
1965-02-01			0.00
1965-02-02			0.00
1965-02-03			0.00
1965-02-04			0.00
1965-02-05			0.00
1965-02-06			0.00
1965-02-07			0.00
1965-02-08			0.00
1965-02-09			0.00
1965-02-10			0.00
1965-02-11			0.00
1965-02-12			0.00
1965-02-13			0.00
1965-02-14			0.00
1965-02-15			0.00
1965-02-16			0.00
1965-02-17			0.00
1965-02-18			0.00
1965-02-19			0.00
1965-02-20			0.00
1965-02-21			0.00
1965-02-22			0.00
1965-02-23			0.00
1965-02-24			0.00
1965-02-25			0.00
1965-02-26			0.00
1965-02-27			0.00
1965-02-28			0.00
1965-03-01			0.00
1965-03-02			0.00
1965-03-03			0.00
1965-03-04			0.00
1965-03-05			0.00
1965-03-06			0.00
1965-03-07			0.00
1965-03-08			0.00
1965-03-09			0.00
1965-03-10			0.00
1965-03-11			0.00
1965-03-12			0.00
1965-03-13			0.00
1965-03-14			0.00
1965-03-15			0.00
1965-03-16			0.00
1965-03-17			0.00
1965-03-18			0.00
1965-03-19			0.00
1965-03-20			0.00
1965-03-21			0.00
1965-03-22			0.00
1965-03-23			0.00
1965-03-24			0.00
1965-03-25			0.00
1965-03-26			0.00
1965-03-27			0.00
1965-03-28			0.00
1965-03-29			0.00
1965-03-30			0.00
1965-03-31			0.00
1965-04-01			0.00
1965-04-02			0.00
1965-04-03			0.

611. 391. 10. 29. 8. 2.

NO. 0	HR. MM	PERIOD	RAIN	EXCS	LOSS	END-OF-PERIOD FLOW COMP 0	70.00	HR. MM	PERIOD	RAIN	EXCS	LOSS	COMP 0
1.01	.05	1	.01	0.00	.01	0.	1.01	12.45	151	.21	.20	.00	17.00
1.01	.10	2	.01	0.00	.01	0.	1.01	12.46	152	.21	.20	.00	17.00
1.01	.15	3	.01	0.00	.01	0.	1.01	12.45	153	.21	.20	.00	17.00
1.01	.20	4	.01	0.00	.01	0.	1.01	12.46	154	.21	.20	.00	17.00
1.01	.25	5	.01	0.00	.01	0.	1.01	12.45	155	.21	.20	.00	17.00
1.01	.30	6	.01	0.00	.01	0.	1.01	13.00	156	.21	.20	.00	17.00
1.01	.35	7	.01	0.00	.01	0.	1.01	13.05	157	.21	.20	.00	17.00
1.01	.40	8	.01	0.00	.01	0.	1.01	13.10	158	.21	.20	.00	17.00
1.01	.45	9	.01	0.00	.01	0.	1.01	13.15	159	.21	.20	.00	17.00
1.01	.50	10	.01	0.00	.01	0.	1.01	13.20	160	.21	.20	.00	17.00
1.01	.55	11	.01	0.00	.01	0.	1.01	13.25	161	.21	.20	.00	17.00
1.01	1.00	12	.01	0.00	.01	0.	1.01	13.30	162	.21	.20	.00	17.00
1.01	1.05	13	.01	0.00	.01	0.	1.01	13.35	163	.21	.20	.00	17.00
1.01	1.10	14	.01	0.00	.01	0.	1.01	13.40	164	.21	.20	.00	17.00
1.01	1.15	15	.01	0.00	.01	0.	1.01	13.45	165	.21	.20	.00	17.00
1.01	1.20	16	.01	0.00	.01	0.	1.01	13.50	166	.21	.20	.00	17.00
1.01	1.25	17	.01	0.00	.01	0.	1.01	13.55	167	.21	.20	.00	17.00
1.01	1.30	18	.01	0.00	.01	0.	1.01	14.00	168	.21	.20	.00	17.00
1.01	1.35	19	.01	0.00	.01	0.	1.01	14.05	169	.21	.20	.00	17.00
1.01	1.40	20	.01	0.00	.01	0.	1.01	14.10	170	.21	.20	.00	17.00
1.01	1.45	21	.01	0.00	.01	0.	1.01	14.15	171	.21	.20	.00	17.00
1.01	1.50	22	.01	0.00	.01	0.	1.01	14.20	172	.21	.20	.00	17.00
1.01	1.55	23	.01	0.00	.01	0.	1.01	14.25	173	.21	.20	.00	17.00
1.01	2.00	24	.01	0.00	.01	0.	1.01	14.30	174	.21	.20	.00	17.00
1.01	2.05	25	.01	0.00	.01	0.	1.01	14.35	175	.21	.20	.00	17.00
1.01	2.10	26	.01	0.00	.01	0.	1.01	14.40	176	.21	.20	.00	17.00
1.01	2.15	27	.01	0.00	.01	0.	1.01	14.45	177	.21	.20	.00	17.00
1.01	2.20	28	.01	0.00	.01	0.	1.01	14.50	178	.21	.20	.00	17.00
1.01	2.25	29	.01	0.00	.01	0.	1.01	14.55	179	.21	.20	.00	17.00
1.01	2.30	30	.01	0.00	.01	0.	1.01	15.00	180	.21	.20	.00	17.00
1.01	2.35	31	.01	0.00	.01	0.	1.01	15.05	181	.21	.20	.00	17.00
1.01	2.40	32	.01	0.00	.01	0.	1.01	15.10	182	.21	.20	.00	17.00
1.01	2.45	33	.01	0.00	.01	0.	1.01	15.15	183	.21	.20	.00	17.00
1.01	2.50	34	.01	0.00	.01	0.	1.01	15.20	184	.21	.20	.00	17.00
1.01	2.55	35	.01	0.00	.01	0.	1.01	15.25	185	.21	.20	.00	17.00
1.01	3.00	36	.01	0.00	.01	0.	1.01	15.30	186	.21	.20	.00	17.00
1.01	3.05	37	.01	0.00	.01	0.	1.01	15.35	187	.21	.20	.00	17.00
1.01	3.10	38	.01	0.00	.01	0.	1.01	15.40	188	.21	.20	.00	17.00
1.01	3.15	39	.01	0.00	.01	0.	1.01	15.45	189	.21	.20	.00	17.00
1.01	3.20	40	.01	0.00	.01	0.	1.01	15.50	190	.21	.20	.00	17.00
1.01	3.25	41	.01	0.00	.01	0.	1.01	15.55	191	.21	.20	.00	17.00
1.01	3.30	42	.01	0.00	.01	0.	1.01	16.00	192	.21	.20	.00	17.00
1.01	3.35	43	.01	0.00	.01	0.	1.01	16.05	193	.21	.20	.00	17.00
1.01	3.40	44	.01	0.00	.01	0.	1.01	16.10	194	.21	.20	.00	17.00
1.01	3.45	45	.01	0.00	.01	0.	1.01	16.15	195	.21	.20	.00	17.00
1.01	3.50	46	.01	0.00	.01	0.	1.01	16.20	196	.21	.20	.00	17.00
1.01	3.55	47	.01	0.00	.01	0.	1.01	16.25	197	.21	.20	.00	17.00
1.01	4.00	48	.01	0.00	.01	0.	1.01	16.30	198	.21	.20	.00	17.00
1.01	4.05	49	.01	0.00	.01	0.	1.01	16.35	199	.21	.20	.00	17.00
1.01	4.10	50	.01	0.00	.01	0.	1.01	16.40	200	.21	.20	.00	17.00
1.01	4.15	51	.01	0.00	.01	0.	1.01	16.45	201	.21	.20	.00	17.00
1.01	4.20	52	.01	0.00	.01	0.	1.01	16.50	202	.21	.20	.00	17.00
1.01	4.25	53	.01	0.00	.01	0.	1.01	16.55	203	.21	.20	.00	17.00
1.01	4.30	54	.01	0.00	.01	0.	1.01	17.00	204	.21	.20	.00	17.00
1.01	4.35	55	.01	0.00	.01	0.	1.01	17.05	205	.21	.20	.00	17.00
1.01	4.40	56	.01	0.00	.01	0.	1.01	17.10	206	.21	.20	.00	17.00
1.01	4.45	57	.01	0.00	.01	0.	1.01	17.15	207	.21	.20	.00	17.00
1.01	4.50	58	.01	0.00	.01	0.	1.01	17.20	208	.21	.20	.00	17.00
1.01	4.55	59	.01	0.00	.01	0.	1.01	17.25	209	.21	.20	.00	17.00
1.01	4.60	60	.01	0.00	.01	0.	1.01	17.30	210	.21	.20	.00	17.00
1.01	4.65	61	.01	0.00	.01	0.	1.01	17.35	211	.21	.20	.00	17.00
1.01	4.70	62	.01	0.00	.01	0.	1.01	17.40	212	.21	.20	.00	17.00
1.01	4.75	63	.01	0.00	.01	0.	1.01	17.45	213	.21	.20	.00	17.00
1.01	4.80	64	.01	0.00	.01	0.	1.01	17.50	214	.21	.20	.00	17.00
1.01	4.85	65	.01	0.00	.01	0.	1.01	17.55	215	.21	.20	.00	17.00
1.01	4.90	66	.01	0.00	.01	0.	1.01	18.00	216	.21	.20	.00	17.00
1.01	4.95	67	.01	0.00	.01	0.	1.01	18.05	217	.21	.20	.00	17.00
1.01	5.00	68	.01	0.00	.01	0.	1.01	18.10	218	.21	.20	.00	17.00
1.01	5.05	69	.01	0.00	.01	0.	1.01	18.15	219	.21	.20	.00	17.00
1.01	5.10	70	.01	0.00	.01	0.	1.01	18.20	220	.21	.20	.00	17.00
1.01	5.15	71	.01	0.00	.01	0.	1.01	18.25	221	.21	.20	.00	17.00
1.01	5.20	72	.01	0.00	.01	0.	1.01	18.30	222	.21	.20	.00	17.00
1.01	5.25	73	.01	0.00	.01	0.	1.01	18.35	223	.21	.20	.00	17.00
1.01	5.30	74	.01	0.00	.01	0.	1.01	18.40	224	.21	.20	.00	17.00
1.01	5.35	75	.01	0.00	.01	0.	1.01	18.45	225	.21	.20	.00	17.00
1.01	5.40	76	.01	0.00	.01	0.	1.01	18.50	226	.21	.20	.00	17.00
1.01	5.45	77	.01	0.00	.01	0.	1.01	18.55	227	.21	.20	.00	17.00
1.01	5.50	78	.01	0.00	.01	0.	1.01	19.00	228	.21	.20	.00	17.00
1.01	5.55	79	.01	0.00	.01	0.	1.01	19.05	229	.21	.20	.00	17.00
1.01	5.60	80	.01	0.00	.01	0.	1.01	19.10	230	.21	.20	.00	17.00
1.01	5.65	81	.01	0.00	.01	0.	1.01	19.15	231	.21	.20	.00	17.00
1.01	5.70	82	.01	0.00	.01	0.	1.01	19.20	232	.21	.20	.00	17.00
1.01	5.75	83	.01	0.00	.01	0.	1.01	19.25	233	.21	.20	.00	17.00
1.01	5.80	84	.01	0.00	.01	0.	1.01	19.30	234	.21	.20	.00	17.00
1.01	5.85	85	.01	0.00	.01	0.	1.01	19.35	235	.21	.20	.00	17.00
1.01	5.90	86	.01	0.00	.01	0.	1.01	19.40	236	.21	.20	.00	17.00
1.01	5.95	87	.01	0.00	.01	0.	1.01	19.45	237	.21	.20	.00	17.00
1.01	6.00	88	.01	0.00	.01	0.	1.01	19.50	238	.21	.20	.00	17.00
1.01	6.05	89	.01	0.00	.01	0.	1.01	19.55	239	.21	.20	.00	17.00
1.01	6.10	90	.01	0.00	.01	0.	1.01	20.00	240	.21	.20	.00	17.00
1.01	6.15	91	.01	0.00	.01	0.	1.01	20.05	241	.21	.20	.00	17.00
1.01	6.20	92	.01	0.00	.01	0.	1.01	20.10	242	.21	.20	.00	17.00
1.01	6.25	93	.01	0.00	.01	0.	1.01	20.15	243	.21	.20	.00	17.00
1.01	6.30	94	.01	0.00	.01	0.	1.01	20.20	244	.21	.20	.00	17.00
1.01	6.35	95	.01	0.00	.01	0.	1.01	20.25	245	.21	.20	.00	17.00
1.01	6.40	96	.01	0.00	.01	0.	1.01	20.30	246	.21	.20	.00	17.00
1.01	6.45	97	.01	0.00	.01	0.	1.01	20.35	247	.21	.20	.00	17.00
1.01	6.50	98	.01	0.00	.01	0.	1.01	20.40	248	.21	.20	.00	17.00
1.01	6.55	99	.01	0.00	.01	0.	1.01	20.45	249	.21	.20	.00	17.00
1.01	6.60	100	.01	0.00	.01	0.	1.01	20.50	250	.21	.20	.00	17.00

1.01	4.40	5.0	51	0.01	0.01	9.	1.01	17.10	206	.23	.23	.00	270.
1.01	4.46	57	57	0.01	0.04	10.	1.01	17.15	207	.23	.23	.00	269.
1.01	4.50	58	58	0.01	0.04	10.	1.01	17.20	208	.23	.23	.00	268.
1.01	4.55	59	59	0.01	0.04	12.	1.01	17.25	209	.23	.23	.00	267.
1.01	4.60	60	60	0.01	0.04	10.	1.01	17.30	210	.23	.23	.00	266.
1.01	4.65	61	61	0.01	0.04	10.	1.01	17.35	211	.23	.23	.00	265.
1.01	4.70	62	62	0.01	0.04	10.	1.01	17.40	212	.23	.23	.00	264.
1.01	4.75	63	63	0.01	0.04	10.	1.01	17.45	213	.23	.23	.00	263.
1.01	4.80	64	64	0.01	0.04	10.	1.01	17.50	214	.23	.23	.00	262.
1.01	4.85	65	65	0.01	0.04	10.	1.01	17.55	215	.23	.23	.00	261.
1.01	4.90	66	66	0.01	0.04	10.	1.01	18.00	216	.23	.23	.00	260.
1.01	4.95	67	67	0.01	0.04	10.	1.01	18.05	217	.02	.02	.00	139.
1.01	5.00	68	68	0.01	0.04	11.	1.01	18.10	218	.02	.02	.00	138.
1.01	5.05	69	69	0.01	0.04	11.	1.01	18.15	219	.02	.02	.00	137.
1.01	5.10	70	70	0.01	0.04	11.	1.01	18.20	220	.02	.02	.00	136.
1.01	5.15	71	71	0.01	0.04	11.	1.01	18.25	221	.02	.02	.00	135.
1.01	5.20	72	72	0.01	0.04	11.	1.01	18.30	222	.02	.02	.00	134.
1.01	5.25	73	73	0.01	0.04	11.	1.01	18.35	223	.02	.02	.00	133.
1.01	5.30	74	74	0.01	0.04	11.	1.01	18.40	224	.02	.02	.00	132.
1.01	5.35	75	75	0.01	0.04	11.	1.01	18.45	225	.02	.02	.00	131.
1.01	5.40	76	76	0.01	0.04	11.	1.01	18.50	226	.02	.02	.00	130.
1.01	5.45	77	77	0.01	0.04	11.	1.01	18.55	227	.02	.02	.00	129.
1.01	5.50	78	78	0.01	0.04	11.	1.01	19.00	228	.02	.02	.00	128.
1.01	5.55	79	79	0.01	0.04	11.	1.01	19.05	229	.02	.02	.00	127.
1.01	5.60	80	80	0.01	0.04	11.	1.01	19.10	230	.02	.02	.00	126.
1.01	5.65	81	81	0.01	0.04	11.	1.01	19.15	231	.02	.02	.00	125.
1.01	5.70	82	82	0.01	0.04	11.	1.01	19.20	232	.02	.02	.00	124.
1.01	5.75	83	83	0.01	0.04	11.	1.01	19.25	233	.02	.02	.00	123.
1.01	5.80	84	84	0.01	0.04	11.	1.01	19.30	234	.02	.02	.00	122.
1.01	5.85	85	85	0.01	0.04	11.	1.01	19.35	235	.02	.02	.00	121.
1.01	5.90	86	86	0.01	0.04	11.	1.01	19.40	236	.02	.02	.00	120.
1.01	5.95	87	87	0.01	0.04	11.	1.01	19.45	237	.02	.02	.00	119.
1.01	6.00	88	88	0.01	0.04	11.	1.01	19.50	238	.02	.02	.00	118.
1.01	6.05	89	89	0.01	0.04	11.	1.01	19.55	239	.02	.02	.00	117.
1.01	6.10	90	90	0.01	0.04	11.	1.01	20.00	240	.02	.02	.00	116.
1.01	6.15	91	91	0.01	0.04	11.	1.01	20.05	241	.02	.02	.00	115.
1.01	6.20	92	92	0.01	0.04	11.	1.01	20.10	242	.02	.02	.00	114.
1.01	6.25	93	93	0.01	0.04	11.	1.01	20.15	243	.02	.02	.00	113.
1.01	6.30	94	94	0.01	0.04	11.	1.01	20.20	244	.02	.02	.00	112.
1.01	6.35	95	95	0.01	0.04	11.	1.01	20.25	245	.02	.02	.00	111.
1.01	6.40	96	96	0.01	0.04	11.	1.01	20.30	246	.02	.02	.00	110.
1.01	6.45	97	97	0.01	0.04	11.	1.01	20.35	247	.02	.02	.00	109.
1.01	6.50	98	98	0.01	0.04	11.	1.01	20.40	248	.02	.02	.00	108.
1.01	6.55	99	99	0.01	0.04	11.	1.01	20.45	249	.02	.02	.00	107.
1.01	6.60	100	100	0.01	0.04	11.	1.01	20.50	250	.02	.02	.00	106.
1.01	6.65	101	101	0.01	0.04	11.	1.01	20.55	251	.02	.02	.00	105.
1.01	6.70	102	102	0.01	0.04	11.	1.01	21.00	252	.02	.02	.00	104.
1.01	6.75	103	103	0.01	0.04	11.	1.01	21.05	253	.02	.02	.00	103.
1.01	6.80	104	104	0.01	0.04	11.	1.01	21.10	254	.02	.02	.00	102.
1.01	6.85	105	105	0.01	0.04	11.	1.01	21.15	255	.02	.02	.00	101.
1.01	6.90	106	106	0.01	0.04	11.	1.01	21.20	256	.02	.02	.00	100.
1.01	6.95	107	107	0.01	0.04	11.	1.01	21.25	257	.02	.02	.00	99.
1.01	7.00	108	108	0.01	0.04	11.	1.01	21.30	258	.02	.02	.00	98.
1.01	7.05	109	109	0.01	0.04	11.	1.01	21.35	259	.02	.02	.00	97.
1.01	7.10	110	110	0.01	0.04	11.	1.01	21.40	260	.02	.02	.00	96.
1.01	7.15	111	111	0.01	0.04	11.	1.01	21.45	261	.02	.02	.00	95.
1.01	7.20	112	112	0.01	0.04	11.	1.01	21.50	262	.02	.02	.00	94.
1.01	7.25	113	113	0.01	0.04	11.	1.01	21.55	263	.02	.02	.00	93.
1.01	7.30	114	114	0.01	0.04	11.	1.01	22.00	264	.02	.02	.00	92.
1.01	7.35	115	115	0.01	0.04	11.	1.01	22.05	265	.02	.02	.00	91.

1.01	9.40	116	.07	.07	.00	16.	1.01	22.10	265	.02	.02	.00	267
1.01	9.40	117	.07	.07	.00	16.	1.01	22.15	267	.02	.02	.00	269
1.01	9.40	118	.07	.07	.00	16.	1.01	22.20	268	.02	.02	.00	270
1.01	9.40	119	.07	.07	.00	16.	1.01	22.25	269	.02	.02	.00	271
1.01	9.40	120	.07	.07	.00	16.	1.01	22.30	270	.02	.02	.00	272
1.01	10.00	121	.07	.07	.00	16.	1.01	22.35	271	.02	.02	.00	273
1.01	10.05	122	.07	.07	.00	16.	1.01	22.40	272	.02	.02	.00	274
1.01	10.10	123	.07	.07	.00	16.	1.01	22.45	273	.02	.02	.00	275
1.01	10.15	124	.07	.07	.00	16.	1.01	22.50	274	.02	.02	.00	276
1.01	10.20	125	.07	.07	.00	16.	1.01	22.55	275	.02	.02	.00	277
1.01	10.25	126	.07	.07	.00	16.	1.01	23.00	276	.02	.02	.00	278
1.01	10.30	127	.07	.07	.00	16.	1.01	23.05	277	.02	.02	.00	279
1.01	10.35	128	.07	.07	.00	16.	1.01	23.10	278	.02	.02	.00	280
1.01	10.40	129	.07	.07	.00	16.	1.01	23.15	279	.02	.02	.00	281
1.01	10.45	130	.07	.07	.00	16.	1.01	23.20	280	.02	.02	.00	282
1.01	10.50	131	.07	.07	.00	16.	1.01	23.25	281	.02	.02	.00	283
1.01	10.55	132	.07	.07	.00	16.	1.01	23.30	282	.02	.02	.00	284
1.01	11.00	133	.07	.07	.00	16.	1.01	23.35	283	.02	.02	.00	285
1.01	11.05	134	.07	.07	.00	16.	1.01	23.40	284	.02	.02	.00	286
1.01	11.10	135	.07	.07	.00	16.	1.01	23.45	285	.02	.02	.00	287
1.01	11.15	136	.07	.07	.00	16.	1.01	23.50	286	.02	.02	.00	288
1.01	11.20	137	.07	.07	.00	16.	1.01	23.55	287	.02	.02	.00	289
1.01	11.25	138	.07	.07	.00	16.	1.01	23.60	288	.02	.02	.00	290
1.01	11.30	139	.07	.07	.00	16.	1.02	0.00	289	.02	.02	.00	291
1.01	11.35	140	.07	.07	.00	16.	1.02	.05	290	.00	.00	.00	292
1.01	11.40	141	.07	.07	.00	16.	1.02	.10	291	.00	.00	.00	293
1.01	11.45	142	.07	.07	.00	16.	1.02	.15	292	.00	.00	.00	294
1.01	11.50	143	.07	.07	.00	16.	1.02	.20	293	.00	.00	.00	295
1.01	11.55	144	.07	.07	.00	16.	1.02	.25	294	.00	.00	.00	296
1.01	12.00	145	.07	.07	.00	16.	1.02	.30	295	.00	.00	.00	297
1.01	12.05	146	.07	.07	.00	16.	1.02	.35	296	.00	.00	.00	298
1.01	12.10	147	.07	.07	.00	16.	1.02	.40	297	.00	.00	.00	299
1.01	12.15	148	.07	.07	.00	16.	1.02	.45	298	.00	.00	.00	300
1.01	12.20	149	.07	.07	.00	16.	1.02	.50	299	.00	.00	.00	301
1.01	12.25	150	.07	.07	.00	16.	1.02	.55	300	.00	.00	.00	302
1.01	12.30	151	.07	.07	.00	16.	1.02	1.00	301	.00	.00	.00	303

SUM 32.37 31.01 1.16 357601

(823.11 793.11) 29.16 1012.72

TOTAL VOLUME

72-HOUR

4-HOUR

PLAN

2392.4

184.

3034

119.

25755.

1012.

31.01

192400

245.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

304.

PMF AND ONE-HALF PMF ROUTING

11

HYDROGRAPH ROUTING

ROUTE HYDROGRAPH THROUGH DAM

ISTAO	ICOMP	RECON	ITYPE	JFLT	JPRG	JNAME	ISTAGE	IAUTO
DAM	1	0	2	0	0	1	0	0
ROUTING DATA								
CROSS	AVG	INES	ISAME	IOPT	IPRG		LSNR	
BAC	0.00	1	1	0	0		0	
INSTPS	INSTOL	LAG	ANSKM	X	ISCK	STORA	ISPRAT	
1	0	0	0.000	0.000	0.000	-878.	-1	

STAGE	836.00	836.74	839.00	840.82	841.02	841.72	842.08	842.48	842.00
FLOW	843.69	844.06	845.00	846.00	847.00	848.00	849.00	850.00	851.00

Surface Area	16	17	18	19	20
16	16	17	18	19	20
17	17	18	19	20	21
18	18	19	20	21	22
19	19	20	21	22	23
20	20	21	22	23	24
21	21	22	23	24	25
22	22	23	24	25	26
23	23	24	25	26	27
24	24	25	26	27	28
25	25	26	27	28	29
26	26	27	28	29	30
27	27	28	29	30	31
28	28	29	30	31	32
29	29	30	31	32	33
30	30	31	32	33	34
31	31	32	33	34	35
32	32	33	34	35	36
33	33	34	35	36	37
34	34	35	36	37	38
35	35	36	37	38	39
36	36	37	38	39	40
37	37	38	39	40	41
38	38	39	40	41	42
39	39	40	41	42	43
40	40	41	42	43	44
41	41	42	43	44	45
42	42	43	44	45	46
43	43	44	45	46	47
44	44	45	46	47	48
45	45	46	47	48	49
46	46	47	48	49	50
47	47	48	49	50	51
48	48	49	50	51	52
49	49	50	51	52	53
50	50	51	52	53	54
51	51	52	53	54	55
52	52	53	54	55	56
53	53	54	55	56	57
54	54	55	56	57	58
55	55	56	57	58	59
56	56	57	58	59	60
57	57	58	59	60	61
58	58	59	60	61	62
59	59	60	61	62	63
60	60	61	62	63	64
61	61	62	63	64	65
62	62	63	64	65	66
63	63	64	65	66	67
64	64	65	66	67	68
65	65	66	67	68	69
66	66	67	68	69	70
67	67	68	69	70	71
68	68	69	70	71	72
69	69	70	71	72	73
70	70	71	72	73	74
71	71	72	73	74	75
72	72	73	74	75	76
73	73	74	75	76	77
74	74	75	76	77	78
75	75	76	77	78	79
76	76	77	78	79	80
77	77	78	79	80	81
78	78	79	80	81	82
79	79	80	81	82	83
80	80	81	82	83	84
81	81	82	83	84	85
82	82	83	84	85	86
83	83	84	85	86	87
84	84	85	86	87	88
85	85	86	87	88	89
86	86	87	88	89	90
87	87	88	89	90	91
88	88	89	90	91	92
89					

1974

NAME	AGE	SEX	REL	DATE	TIME	PLACE	REMARKS
JOHN J. BROWN	45	M	H	1945	10:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	11:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	11:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	12:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	12:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	13:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	13:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	14:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	14:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	15:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	15:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	16:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	16:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	17:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	17:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	18:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	18:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	19:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	19:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	20:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	20:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	21:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	21:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	22:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	22:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	23:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	23:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	00:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	00:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	01:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	01:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	02:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	02:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	03:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	03:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	04:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	04:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	05:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	05:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	06:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	06:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	07:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	07:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	08:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	08:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	09:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	09:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	10:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	10:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	11:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	11:30	NEW YORK	ARRIVED
MARY J. BROWN	42	F	W	1945	12:00	NEW YORK	ARRIVED
JOHN J. BROWN	45	M	H	1945	12:30	NEW YORK	

0250	0250	0300	0380	0390	0400	0420	0500
------	------	------	------	------	------	------	------

[illegible]

DATA

70NEL 100D EXPD DAWID

[illegible]

STATION: BANG PLAN 10, RAYD 1

END OF PERIOD HYDROGRAPH OBSERVATES

NO. 1000

1. The first part of the document is a list of names and titles, including "The Hon. Mr. Justice" and "The Hon. Mr. Justice".

10

100

1. The first part of the document is a list of names and titles, including "The Hon. Mr. Justice" and "The Hon. Mr. Justice".

10

100

STORAGE

[illegible]

PEAK OUTPUT IS 2960 AT TIME 15.92 HOURS

100

RUNOFF CALCULATIONS FOR ADDITIONAL DRAINAGE AREA

DATE OF BIRTH - 01-16-1916
PLACE OF BIRTH - WYOMING

UNIT HYDROGRAPH DATA
TCE 0.00 LAGS .04

RECESSION DATA
STRIDE 0.00 QRESN 0.00 RTDOR 1.00

TIME INCREMENT TOO LARGE--INHG IS 84 LAB/25

UNIT HYDROGRAPH 5 END OF PERIOD ORIGINATES TCE 0.00 HOURS LABS .04 VOL 1.00

MO-DA		HR-MN	PERIOD	RAIN	EXCS	LOSS	FAS-OF-PERIOD FLOW		MO-DA	HR-MN	PERIOD	RAIN	EXCS	LOSS	COMP 6	
0							COMP 0									
1.01	0.01	0.01	1	.01	0.00	.01	0.	0.	1.01	12.55	151	.21	.20	.00	11.	11.
1.01	0.10	0.01	2	.01	0.00	.01	0.	0.	1.01	12.50	152	.21	.20	.00	11.	11.
1.01	0.15	0.01	3	.01	0.00	.01	0.	0.	1.01	12.45	153	.21	.20	.00	11.	11.
1.01	0.20	0.01	4	.01	0.00	.01	0.	0.	1.01	12.40	154	.21	.20	.00	11.	11.
1.01	0.25	0.01	5	.01	0.00	.01	0.	0.	1.01	12.35	155	.21	.20	.00	11.	11.
1.01	0.30	0.01	6	.01	0.00	.01	0.	0.	1.01	12.30	156	.21	.20	.00	11.	11.
1.01	0.35	0.01	7	.01	0.00	.01	0.	0.	1.01	12.25	157	.21	.20	.00	11.	11.
1.01	0.40	0.01	8	.01	0.00	.01	0.	0.	1.01	12.20	158	.21	.20	.00	11.	11.
1.01	0.45	0.01	9	.01	0.00	.01	0.	0.	1.01	12.15	159	.21	.20	.00	11.	11.
1.01	0.50	0.01	10	.01	0.00	.01	0.	0.	1.01	12.10	160	.21	.20	.00	11.	11.
1.01	0.55	0.01	11	.01	0.00	.01	0.	0.	1.01	12.05	161	.21	.20	.00	11.	11.
1.01	1.00	0.01	12	.01	0.00	.01	0.	0.	1.01	12.00	162	.21	.20	.00	11.	11.
1.01	1.05	0.01	13	.01	0.00	.01	0.	0.	1.01	11.55	163	.21	.20	.00	11.	11.
1.01	1.10	0.01	14	.01	0.00	.01	0.	0.	1.01	11.50	164	.21	.20	.00	11.	11.
1.01	1.15	0.01	15	.01	0.00	.01	0.	0.	1.01	11.45	165	.21	.20	.00	11.	11.
1.01	1.20	0.01	16	.01	0.00	.01	0.	0.	1.01	11.40	166	.21	.20	.00	11.	11.
1.01	1.25	0.01	17	.01	0.00	.01	0.	0.	1.01	11.35	167	.21	.20	.00	11.	11.
1.01	1.30	0.01	18	.01	0.00	.01	0.	0.	1.01	11.30	168	.21	.20	.00	11.	11.
1.01	1.35	0.01	19	.01	0.00	.01	0.	0.	1.01	11.25	169	.21	.20	.00	11.	11.
1.01	1.40	0.01	20	.01	0.00	.01	0.	0.	1.01	11.20	170	.21	.20	.00	11.	11.
1.01	1.45	0.01	21	.01	0.00	.01	0.	0.	1.01	11.15	171	.21	.20	.00	11.	11.
1.01	1.50	0.01	22	.01	0.00	.01	0.	0.	1.01	11.10	172	.21	.20	.00	11.	11.
1.01	1.55	0.01	23	.01	0.00	.01	0.	0.	1.01	11.05	173	.21	.20	.00	11.	11.
1.01	2.00	0.01	24	.01	0.00	.01	0.	0.	1.01	11.00	174	.21	.20	.00	11.	11.
1.01	2.05	0.01	25	.01	0.00	.01	0.	0.	1.01	10.55	175	.21	.20	.00	11.	11.
1.01	2.10	0.01	26	.01	0.00	.01	0.	0.	1.01	10.50	176	.21	.20	.00	11.	11.
1.01	2.15	0.01	27	.01	0.00	.01	0.	0.	1.01	10.45	177	.21	.20	.00	11.	11.
1.01	2.20	0.01	28	.01	0.00	.01	0.	0.	1.01	10.40	178	.21	.20	.00	11.	11.
1.01	2.25	0.01	29	.01	0.00	.01	0.	0.	1.01	10.35	179	.21	.20	.00	11.	11.
1.01	2.30	0.01	30	.01	0.00	.01	0.	0.	1.01	10.30	180	.21	.20	.00	11.	11.
1.01	2.35	0.01	31	.01	0.00	.01	0.	0.	1.01	10.25	181	.21	.20	.00	11.	11.
1.01	2.40	0.01	32	.01	0.00	.01	0.	0.	1.01	10.20	182	.21	.20	.00	11.	11.
1.01	2.45	0.01	33	.01	0.00	.01	0.	0.	1.01	10.15	183	.21	.20	.00	11.	11.
1.01	2.50	0.01	34	.01	0.00	.01	0.	0.	1.01	10.10	184	.21	.20	.00	11.	11.
1.01	2.55	0.01	35	.01	0.00	.01	0.	0.	1.01	10.05	185	.21	.20	.00	11.	11.
1.01	3.00	0.01	36	.01	0.00	.01	0.	0.	1.01	10.00	186	.21	.20	.00	11.	11.
1.01	3.05	0.01	37	.01	0.00	.01	0.	0.	1.01	09.55	187	.21	.20	.00	11.	11.
1.01	3.10	0.01	38	.01	0.00	.01	0.	0.	1.01	09.50	188	.21	.20	.00	11.	11.
1.01	3.15	0.01	39	.01	0.00	.01	0.	0.	1.01	09.45	189	.21	.20	.00	11.	11.
1.01	3.20	0.01	40	.01	0.00	.01	0.	0.	1.01	09.40	190	.21	.20	.00	11.	11.
1.01	3.25	0.01	41	.01	0.00	.01	0.	0.	1.01	09.35	191	.21	.20	.00	11.	11.
1.01	3.30	0.01	42	.01	0.00	.01	0.	0.	1.01	09.30	192	.21	.20	.00	11.	11.
1.01	3.35	0.01	43	.01	0.00	.01	0.	0.	1.01	09.25	193	.21	.20	.00	11.	11.
1.01	3.40	0.01	44	.01	0.00	.01	0.	0.	1.01	09.20	194	.21	.20	.00	11.	11.
1.01	3.45	0.01	45	.01	0.00	.01	0.	0.	1.01	09.15	195	.21	.20	.00	11.	11.
1.01	3.50	0.01	46	.01	0.00	.01	0.	0.	1.01	09.10	196	.21	.20	.00	11.	11.
1.01	3.55	0.01	47	.01	0.00	.01	0.	0.	1.01	09.05	197	.21	.20	.00	11.	11.
1.01	4.00	0.01	48	.01	0.00	.01	0.	0.	1.01	09.00	198	.21	.20	.00	11.	11.
1.01	4.05	0.01	49	.01	0.00	.01	0.	0.	1.01	08.55	199	.21	.20	.00	11.	11.
1.01	4.10	0.01	50	.01	0.00	.01	0.	0.	1.01	08.50	200	.21	.20	.00	11.	11.

	PEAK	5-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CSF	144	21	7	6	193
Urine	14	1	1	0	15
feces	1	1	1	1	4
inlets	2,169	81,121	51,121	31,121	153,392
mm	627,110	792,680	792,680	792,680	3,003,150
acet	11	11	11	13	46
hours	20	18	18	16	72

HYDROGRAPH AT STA. HUV FOR PLAN 1, RTO 2

[illegible]

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CPS	536.	362.	116.	111.	3342.1
C/S	13.	10.	3.	3.	936.
INCHES		22.01	27.68	27.68	27.68
MM		559.09	703.05	703.05	703.05
ACFT		183.	230.	230.	230.
THOUS CU M		226.	284.	284.	284.

STATION HWY PLAN 1, RATIO 2
END-OF-PEAK HYDROGRAPH ORDINATES

OUTLET

817.3	818.1	817.0	817.9	817.1	817.7	817.6	817.6	817.8	817.4
817.6	817.4	817.3	817.3	817.3	817.3	817.3	817.2	817.2	817.2
817.2	817.2	817.1	817.1	817.1	817.1	817.1	817.0	817.0	817.0
817.0	817.0	816.9	816.9	816.9	816.9	816.8	816.8	816.8	816.8
816.7	816.7	816.7	816.7	816.6	816.6	816.6	816.5	816.5	816.5
816.5	816.5	816.5	816.5	816.4	816.4	816.4	816.3	816.3	816.3
816.3	816.2	816.2	816.2	816.1	816.1	816.1	816.1	816.1	816.0

PEAK OUTFLOW IS 289. AT TIME 16.17 HOURS

FLAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
209.	156.	524	50.	15015.
CFS	4.	1.	1.	423.
INCHES	9.42	12.44	12.44	12.44
AC-FT	239.17	315.87	315.87	315.87
THOUS CU	784	1034	103.	103.
	97.	128.	128.	128.

SUMMARY OF PMF AND ONE-HALF PMF FLOOD ROUTING

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC FEET PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN-RATIO 1	RATIO 2
			1.00	.90
HYDROGRAPH AT	DAM	.19 (.49)	1	2332 (6003)
				1166 (3501)
ROUTED TO	DAM	.19 (.49)	1	1526 (4322)
				295 (859)
HYDROGRAPH AT	HWT	.01 (.02)	1	144 (408)
				72 (204)
COMBINED	HWT	.10 (.26)	1	1613 (4566)
				312 (882)
ROUTED TO	HWT	.10 (.26)	1	534 (1513)
				289 (818)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

ELEVATION
STAGE
OUT/ICW

INITIAL VALUE
818.00
0.
0.

SPILLWAY CREST
415.00
0.
0.

TOP OF DAM
842.00
48.
578.

RATIO OF PMF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	835.72	0.00	37.	534.	0.00	16.17	0.00
.50	828.96	0.00	4.	289.	0.00	16.17	0.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

RATIO OF PHF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF	
						MAX OUTFLOW HOURS	FAILURE HOURS
1.00	842.42	.65	190.	1126.	1.00	15.67	0.00
.50	841.65	0.00	169.	296.	0.00	15.92	0.00

ELEVATION
STORAGE
OUTFLOW

INITIAL VALUE
838.00
104.
0.

SPILLWAY CREST
878.00
104.
0.

TOP OF DAM
842.00
176.
418.

PERCENT OF PMF FLOOD ROUTING
EQUAL TO SPILLWAY CAPACITY

SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT
ROUTE HYDROGRAPH TO
ROUTE HYDROGRAPH AT
COMBINE 2 HYDROGRAPHS AT
ROUTE HYDROGRAPH TO
END OF NETWORK

DAM
LAW
HUY
HUY

.....
 PREPARED BY: HYDROGRAPH PACKAGE (DEC-1)
 IN SAFETY PERSON JULY 1978
 ANY MODIFICATION 26 FEB 79

DATE: 88/07/104
 TIME: 89.05.43.

DAM SAFETY INSPECTION - MISSOURI
 HAUCK LAKE DAM NO. 10989
 PERCENT PMF

JOB SPECIFICATION									
NC	NMR	NRIN	ICAY	INR	IMIN	PETRC	IPLT	IPRT	INSTAN
300	0	5	0	0	0	0	0	-4	0
JUPER NUT LROPT TRACE									
0 0 0 0 0									

MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLANE= 1 NRTIO= 4 LRTIO= 1

PTIOS= .56 .62 .63 .67

SUR-AREA RUNOFF COMPUTATION

RUNOFF CALCULATIONS FOR THE MAIN DRAINAGE AREA

ISTAO ICONF IECOM ICAPE IJPLT IPRT INAME ITRAGE IAUTO
 0 0 0 0 0 0 0 0 0

HYDROGRAPH DATA
 INYOB IUNB IZANEA SHAP TRSDA TRSPO RATIO ISHOW ISAME LOCAL
 1 2 .15 0.00 .15 1.00 0.00 0 0 1 0

PRECIP DATA

R6 R12 R24 R36 R72 R96
 0.00 0.00 0.00 0.00 0.00 0.00

LOSS DATA

STATL CNYSL ALSTM RTIMP
 1.00 0.00 1.00 -1.00 0.00 0.00

UNIT HYDROGRAPH DATA

LAG= .06

REGISTRATION DATA

ATIDPR 1.00

END-OF-PERIOD FLOW

MO-DA MAXIN PERIOD RAIN RATE LGTH

SUM 32.37 31.71 1.18 38964.
(882.11 793.41 29331 1018198)

.....

.....

.....

.....

HYDROGRAPH ROUTING

ROUTE HYDROGRAPH THROUGH DAM

ISYAD ICOMP IECN IIAPE JPL JERT INAME ISTAGE IAUFO
DAM 1 0 0 0 0 0 0 0

ROUTING DATA
IGRES ISAME IGPT IPMP LSTR
1 1 0 0 0

LAG AMSKK X TSM STORA IEPRAI
0 0.000 0.000 0.000 -830. .1

STAGE 830.00 838.74 839.40 840.32 841.02 842.00 842.68 843.14

FLO 0.00 10.00 10.00 60.00 101.00 311.00 449.00 930.00 1500.00 8055.00

SURFACE AREAS 0. 1. 6. 15. 17. 18. 21. 38. 57.

CAPACITY 0. 1. 23. 109. 127. 137. 176. 398. 853.

ELEVATIONS 820. 823. 838. 838. 839. 840. 842. 850. 880.

CREL SPIDB ECUW EUSVL COOL CAREA VEPH
0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

TOPEL DAM DATA
842.00 0.0 0.0 0.0

PEAK OUTFLOW IS 396. AT TIME 15.92 HOURS

PEAK OUTFLOW IS 440. AT TIME 15.88 HOURS

PEAK OUTFLOW IS 480. AT TIME 15.83 HOURS

PEAK OUTFLOW IS 510. AT TIME 15.83 HOURS

.....

.....

.....

.....

.....

INTAD ICOMP ILCON IFAPE IJPLI JPRPT INAME ISTATE IAUPTO
HNY 0 0 0 0 0 1 0 0

INTUG IUNG IARIA SNAP TRSQA TRSPC RATIO ISNOW ISAME LOCAL
1 2 .01 0.00 .01 1.00 0.000 0 1 0

SPEE PNS RA R12 R24 R40 R72 R96
0.00 24.90 100.00 120.00 130.00 0.00 0.00 0.00 0.00

LOSS DATA
LROPT STRMR DLTKR RTIOL ERAIN STRKS RTIOM SINTL CNSTL ALSXK RTIMP
0. 0.00 0.00 1.00 0.00 0.00 1.00 -1.00 -91.00 0.00 0.00

CURVE NO 2 -91.00 WTNSS = -1.00 EFFECT CN = 91.00

UNIT HYDROGRAPH DATA
TC= 0.00 LAC= 0.00

RECESSION DATA
SRTQ= 0.00 OPCSE= 0.00 RTIO= 1.00

MOADA HRMM PERIOD RAIN ERCS LOSS ENC-OF-PERIOD FLOW MUODA HRMM PERIOD RAIN ERCS LOSS COMF 0
SUM 32.37 31.21 1.16 190.5
(228.01 745.61 25.11 53.07)

COMBINE PM OUTFLOW AND ADDITIONAL RUNOFF HYDROGRAPHS

INTAD ICOMP ILCON IFAPE IJPLI JPRPT INAME ISTATE IAUPTO
HNY 0 0 0 0 0 1 0 0

INTUG IUNG IARIA SNAP TRSQA TRSPC RATIO ISNOW ISAME LOCAL
1 2 .01 0.00 .01 1.00 0.000 0 1 0

SPEE PNS RA R12 R24 R40 R72 R96
0.00 24.90 100.00 120.00 130.00 0.00 0.00 0.00 0.00

LOSS DATA
LROPT STRMR DLTKR RTIOL ERAIN STRKS RTIOM SINTL CNSTL ALSXK RTIMP
0. 0.00 0.00 1.00 0.00 0.00 1.00 -1.00 -91.00 0.00 0.00

CURVE NO 2 -91.00 WTNSS = -1.00 EFFECT CN = 91.00

UNIT HYDROGRAPH DATA
TC= 0.00 LAC= 0.00

RECESSION DATA
SRTQ= 0.00 OPCSE= 0.00 RTIO= 1.00

MOADA HRMM PERIOD RAIN ERCS LOSS ENC-OF-PERIOD FLOW MUODA HRMM PERIOD RAIN ERCS LOSS COMF 0
SUM 32.37 31.21 1.16 190.5
(228.01 745.61 25.11 53.07)

FLOW 0.00 45.00 174.00 380.00 461.00 570.00 836.00 1377.80 1984.00 2766.00
 3609.00 4577.00

SURFACE AREA 0. 1. 2. 3. 4. 5.
 CAPACITY 0. 16. 41. 82.
 ELEVATION 819. 820. 830. 840. 850.

CRSL SPMID COOW EXPN ELEV COUL CAREA EXPL
 815.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA
 TOBEL COOB EXFD DAMVIC
 0.0 0.0 0.0

PEAK OUTFLOW IS 380. AT TIME 16.25 HOURS

PEAK OUTFLOW IS 385. AT TIME 16.33 HOURS

PEAK OUTFLOW IS 378. AT TIME 16.33 HOURS

PEAK OUTFLOW IS 391. AT TIME 16.25 HOURS

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIO	RATIOS APPLIED TO FLOWS			
					1	2	3	4
				.58	.62	.63	.67	
HYDROGRAPH AT	DAY	.15	1	1352.	1446.	1469.	1562.	
	(.439)	(38.30)	60.94)	41.60)	44.24)	
ROUTED TO	DAY	.18	1	397.	448.	488.	616.	
	(.32)	(11.23)	12.68)	13.81)	17.44)	
HYDROGRAPH AT	DAY	.01	1	84.	89.	91.	97.	
	(.48)	(2.37)	2.53)	2.57)	2.74)	
2 COMBINED	DAY	.16	1	416.	472.	512.	642.	
	(.49)	(11.85)	13.35)	14.50)	18.17)	
ROUTED TO	DAY	.16	1	346.	365.	378.	394.	
	(.48)	(9.79)	10.33)	10.49)	11.15)	

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1							
ELEVATION		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM	
STORAGE		938.00		838.00		842.00	
OUTFLOW		100.		100.		176.	
		0.		0.		416.	
RATIO OF RESERVOIR PMF		MAXIMUM DEPTH OVER DAM		MAXIMUM STORAGE AC-FT		MAXIMUM OUTFLOW CFS	
.58		0.30		175.		397.	
.62		.08		178.		448.	
.64		.10		178.		488.	
.67		.19		180.		616.	
						DURATION OVER TOP HOURS	
						0.00	
						.33	
						.33	
						.50	
						15.92	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	
						15.83	

..... 1

RELATION OF PMF	MAXIMUM RESERVOIR W-BELLY	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.....			INITIAL VALUE	SPILLWAY CREST		TOP OF DAM	
			815.00	815.00		842.00	
			84	0.		484	
			0.	0.		570.	
458	823.81	0.00	6.	246.	0.00	16.25	0.00
.62	825.11	0.00	8.	365.	0.00	16.13	0.00
.63	825.57	0.00	9.	470.	0.00	16.33	0.00
.67	827.25	0.00	11.	594.	0.00	16.25	0.00

HEC-2 INPUT AND SUMMARY TABLE

.....
 1. NAME: JAMES EARL RAY
 2. DATE: 10/10/68
 3. LOCATION: MOBILE, ALA.
 4. TIME: 10:00 AM

.....
 5. NAME: JAMES EARL RAY
 6. DATE: 10/10/68
 7. LOCATION: MOBILE, ALA.
 8. TIME: 10:00 AM

.....
 9. NAME: JAMES EARL RAY
 10. DATE: 10/10/68
 11. LOCATION: MOBILE, ALA.
 12. TIME: 10:00 AM

.....
 13. NAME: JAMES EARL RAY
 14. DATE: 10/10/68
 15. LOCATION: MOBILE, ALA.
 16. TIME: 10:00 AM

.....
 17. NAME: JAMES EARL RAY
 18. DATE: 10/10/68
 19. LOCATION: MOBILE, ALA.
 20. TIME: 10:00 AM

.....
 21. NAME: JAMES EARL RAY
 22. DATE: 10/10/68
 23. LOCATION: MOBILE, ALA.
 24. TIME: 10:00 AM

.....
 25. NAME: JAMES EARL RAY
 26. DATE: 10/10/68
 27. LOCATION: MOBILE, ALA.
 28. TIME: 10:00 AM

.....
 29. NAME: JAMES EARL RAY
 30. DATE: 10/10/68
 31. LOCATION: MOBILE, ALA.
 32. TIME: 10:00 AM

.....
 33. NAME: JAMES EARL RAY
 34. DATE: 10/10/68
 35. LOCATION: MOBILE, ALA.
 36. TIME: 10:00 AM

.....
 37. NAME: JAMES EARL RAY
 38. DATE: 10/10/68
 39. LOCATION: MOBILE, ALA.
 40. TIME: 10:00 AM

.....
 41. NAME: JAMES EARL RAY
 42. DATE: 10/10/68
 43. LOCATION: MOBILE, ALA.
 44. TIME: 10:00 AM

.....
 45. NAME: JAMES EARL RAY
 46. DATE: 10/10/68
 47. LOCATION: MOBILE, ALA.
 48. TIME: 10:00 AM

.....
 49. NAME: JAMES EARL RAY
 50. DATE: 10/10/68
 51. LOCATION: MOBILE, ALA.
 52. TIME: 10:00 AM

.....
 53. NAME: JAMES EARL RAY
 54. DATE: 10/10/68
 55. LOCATION: MOBILE, ALA.
 56. TIME: 10:00 AM

.....
 57. NAME: JAMES EARL RAY
 58. DATE: 10/10/68
 59. LOCATION: MOBILE, ALA.
 60. TIME: 10:00 AM

[illegible]

DATE
ILME